

**NM OIL CONSERVATION  
ARTESIA DISTRICT**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

JUN 14 2016

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED** Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

0AB1616741171 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <u>260737</u>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Legg Federal 001	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-04734
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	27	22S	30E	540	North	2300	East	Eddy

Latitude 32.369037° Longitude -103.867859°

**NATURE OF RELEASE**

Type of Release	Crude Oil and Produced Water	Volume of Release	0.5 bbl oil 9 bbls PW	Volume Recovered	0 bbl
Source of Release	Test Heater	Date and Hour of Occurrence	6/9/2016 time unknown	Date and Hour of Discovery	6/9/2016 7 pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	N/A	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* A manway gasket failed on the test heater unit. Unit was drained and isolated for repair.					
Describe Area Affected and Cleanup Action Taken.* The leak affected 4,056 sq. ft. of caliche pad, most of which was an overspray.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy C. Ruth	Approved by Environmental Specialist <u>Signed By: Mike Brannon</u>	
Title: EHS Remediation Specialist	Approval Date: <u>6/14/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: ACRuth@basspet.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO</b>	
Date: 6/14/2016 Phone: 432-661-0571	<b>LATER THAN: <u>7/15/16</u></b>	

\* Attach Additional Sheets If Necessary

ARP-3744