

State of New Mexico  
Energy, Minerals and Natural Resources Department

Susana Martinez  
Governor

David Martin  
Cabinet Secretary

Tony Delfin  
Deputy Cabinet Secretary

David Catanach, Director  
Oil Conservation Division



**\*Response Required - Deadline Enclosed\***

*Field Inspection Program*  
*"Preserving the Integrity of Our Environment"*

28-Jun-16

LARRY MARKER DBA MARKER OIL  
PO BOX 3188  
Roswell NM 88202-8202

**LETTER OF VIOLATION - Inspection**

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

**INSPECTION DETAIL SECTION**

NORTH SQUARE LAKE UNIT No.092				P-27-16S-31E	30-015-04887-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/28/2016	Routine/Periodic	Tony Morales	Yes	No	10/1/2016	iTM1618038797
Violations						
General Housekeeping (Rule 114)						
Comments on Inspection:		OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELL HEAD. CONTAMINATED MATERIAL ON LOCATION				

NORTH SQUARE LAKE UNIT No.025				A-29-16S-31E	30-015-04913-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/28/2016	Routine/Periodic	Tony Morales	Yes	No	10/1/2016	iTM1618047022
Violations						
General Housekeeping (Rule 114)						
Comments on Inspection:		OK. All Equipment and Location in Good Shape. PJO. STAINING AROUND WELL HEAD STAINED AREA APPROX 10' X 10'				

**NORTH SQUARE LAKE UNIT No.174**

P-34-16S-31E

30-015-04988-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/28/2016	Routine/Periodic	Tony Morales	Yes	No	10/1/2016	iTM1618040088
<b>Violations</b>						
General Housekeeping (Rule 114)						

**Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELL HEAD. STAINED AREA APPROX 15' X 30'

**NORTH SQUARE LAKE UNIT No.067**

K-27-16S-31E

30-015-10121-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/28/2016	Routine/Periodic	Tony Morales	Yes	No	10/1/2016	iTM1618043223
<b>Violations</b>						
General Housekeeping (Rule 114)						

**Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJ. CONTAMINATED MATERIAL ON LOCATION LOCATION SIGN DOWN.

**NORTH SQUARE LAKE UNIT No.091**

O-27-16S-31E

30-015-10270-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/28/2016	Routine/Periodic	Tony Morales	Yes	No	10/1/2016	iTM1618042496
<b>Violations</b>						
General Housekeeping (Rule 114)						

**Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELL HEAD+.. STAINED AREA APPROX 10' X 10'

**NORTH SQUARE LAKE UNIT No.114**

C-34-16S-31E

30-015-10271-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/28/2016	Routine/Periodic	Tony Morales	Yes	No	10/1/2016	iTM1618040763
<b>Violations</b>						
General Housekeeping (Rule 114)						

**Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELL HEAD. CONTAMINATED MATERIAL NEXT TO WELL HEAD

**NORTH SQUARE LAKE UNIT No.116**

A-34-16S-31E

30-015-10272-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/28/2016	Routine/Periodic	Tony Morales	Yes	No	10/1/2016	iTM1618038453
<b>Violations</b>						
General Housekeeping (Rule 114)						

**Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELL HEAD. CONTAMINATED MATERIAL ON LOCATION

**NORTH SQUARE LAKE UNIT No.156**

J-34-16S-31E


30-015-21771-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/28/2016	Routine/Periodic	Tony Morales	Yes	No	10/1/2016	iTM1618039599
<b>Violations</b>						
General Housekeeping (Rule 114)						

**Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJO. STAINING AROUND WELL HEAD STAINED AREA APPROX 10' X 10'

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

A handwritten signature in black ink that reads "Tony Morales, CO". The signature is fluid and cursive, with the initials "CO" written at the end.

Artesia OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.  
\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.