State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary

David Catanach, Director Oil Conservation Division

Tony Delfin

Deputy Cabinet Secretary



Response Required - Deadline Enclosed

27-Jun-16

CANYON E & P COMPANY

4925 GREENVILLE AVE SUITE 900 DALLAS TX 75206-

LETTER OF VIOLATION - Inactive Well(s)

Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 201 of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that ther well is no longer usable (e.g., a dry hole), or one year after last production. To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are available:

- 1. Immediately restore the well(s) to production, injection or disposal as applicable.
- 2. Request 'Temporary Abandoned' status pursuant to Rule 203, which requires that you set a plug and conduct a mechanical integrity test.
- 3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 202, proceed with plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

IDLE WELL INSPECTION DETAIL SECTION

NORTHEAST SOUARE LAKE PREMIER UNIT 007

P-3-16S-31E

30-015-04787-00-00

Inspection No. iTM1617644758

6/24/2016 12:25:53 PM

Corrective Action Due by: 9/27/2016

Inspection Date: Type Inspection

Inspector

Violation?

*Significant Non-Compliance?

Routine/Periodic

Tony Morales

Yes

No

Comments on Inspection:

Idle Well (Rule 19.15.25.8)

NO PJ. WELL HEAD. NO LOCATION

SIGN.

Inspection No. iTM1617647739

NORTHEAST SOUARE LAKE PREMIER UNIT 005

P-3-16S-31E

30-015-04788-00-00

Inspection Date: 6/24/2016 1:15:35 PM Corrective Action Due by: 9/27/2016 Type Inspection Inspector Violation? *Significant Non-Compliance? Routine/Periodic Tony Morales Yes No Comments on Inspection: Idle Well (Rule 19,15,25.8) NO PJ. WELL HEAD. NO LOCATION SIGN. NORTHEAST SOUARE LAKE O-3-16S-31E 30-015-04792-00-00 Inspection No. iTM1617644230 PREMIER UNIT 006 Inspection Date: Corrective Action Due by: 9/27/2016 6/24/2016 12:17:08 PM Type Inspection Inspector Violation? *Significant Non-Compliance? Routine/Periodic **Tony Morales** Yes Comments on Inspection: NO PJ. WELL HEAD. NO LOCATION Idle Well (Rule 19.15.25.8) SIGN. NORTHEAST SOUARE LAKE J-3-16S-31E 30-015-04793-00-00 Inspection No. iTM1617646026 PREMIER UNIT 002 Inspection Date: Corrective Action Due by: 9/27/2016 6/24/2016 12:47:03 PM Type Inspection Violation? *Significant Non-Compliance? Inspector Routine/Periodic Yes Tony Morales Comments on Inspection: NO PJ. WELL HEAD, NO LOCATION Idle Well (Rule 19.15.25.8) SIGN. ROAD WASHED OUT NORTHEAST SQUARE LAKE K-3-16S-31E 30-015-04794-00-00 Inspection No. iTM1617646852 PREMIER UNIT 003 Corrective Action Due by: 9/27/2016 Inspection Date: 6/24/2016 1:00:49 PM *Significant Non-Compliance? Type Inspection Inspector Violation? Routine/Periodic Tony Morales Yes NO PJ. WELL HEAD. NO LOCATION Comments on Inspection: Idle Well (Rule 19.15.25.8) SIGN. Inspection No. iTM1617648243 NORTHEAST SOUARE LAKE A-9-16S-31E 30-015-04831-00-00 PREMIER UNIT 012 Inspection Date: 6/24/2016 1:24:01 PM Corrective Action Due by: 9/27/2016 Type Inspection Violation? *Significant Non-Compliance? Inspector Routine/Periodic Yes No Tony Morales Comments on Inspection: NO PJ. WELL HEAD. NO LOCATION Idle Well (Rule 19.15.25.8) SIGN. FLOW LINE ON LOCATION 30-015-04839-00-00 Inspection No. iTM1617643386 NORTHEAST SOUARE LAKE D-10-16S-31E PREMIER UNIT 011 Inspection Date: Corrective Action Due by: 9/27/2016 6/24/2016 12:03:03 PM *Significant Non-Compliance? Type Inspection Inspector Violation? Routine/Periodic Tony Morales Yes Comments on Inspection: NO PJ. WELL HEAD. NO LOCATION Idle Well (Rule 19.15.25.8) SIGN. 30-015-04842-00-00 Inspection No. iTM1617925912 NORTHEAST SOUARE LAKE J-10-16S-31E PREMIER UNIT 026 **Inspection Date:** Corrective Action Due by: 9/27/2016 6/24/2016 7:11:46 AM *Significant Non-Compliance? Violation? Type Inspection Inspector No Routine/Periodic Yes **Tony Morales** NO PJ. STAINING AROUND WELL Comments on Inspection: Idle Well (Rule 19.15.25.8) HEAD. FRESH OIL STAINED AREA APPROX. 15' X 20 LOCATION SIGN NOT VISIBLE. Inspection No. iTM1617648697 NORTHEAST SQUARE LAKE O-4-16S-31E 30-015-25943-00-00 PREMIER UNIT 031

Inspection Date:

6/24/2016 1:31:34 PM

Corrective Action Due by: 9/27/2016

Type Inspection

Inspector

Violation? *Significant Non-Compliance?

Routine/Periodic

Tony Morales

Comments on Inspection:

Idle Well (Rule 19.15.25.8)

Yes

No

SIGN.

NO PJ. WELL HEAD. NO LOCATION

NORTHEAST SQUARE LAKE

N-3-16S-31E

30-015-27560-00-00

Inspection No. iTM1617643834

PREMIER UNIT 030

Inspection Date:

6/24/2016 12:10:30 PM

Corrective Action Due by: 9/27/2016

Type Inspection

Inspector

Violation?

*Significant Non-Compliance?

Routine/Periodic

Tony Morales

Yes

No

Comments on Inspection:

Idle Well (Rule 19.15.25.8)

OF WELL HEAD NO LOCATION SIGN.

NO PJ. WELL HEAD. SUCKER ROD OUT

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely,

Artesia OCD District

^{*} Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas.