


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
With Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Cimarex Energy	Contact	Terry D. Ainsworth
Address	600 Marienfeld Midland, TX 79701	Telephone No.	(575) 390-1388
Facility Name	Etail AD Fed 2	Facility Type	Gas Well
Surface Owner	Mineral Owner	Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	19	24S	26E	2270	North	380	East	Eddy

Latitude 32 12' 13.68" N Longitude 104 19' 29.07 W

NATURE OF RELEASE


Type of Release	Condensate & Water	Volume of Release	67	Volume Recovered	30
Source of Release	Hole in tank bottom	Date and Hour of Occurrence	8/10/12 ???	Date and Hour of Discovery	8/10/12 9:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston			
By Whom?	Terry D. Ainsworth	Date and Hour 8/10/12 10:00 AM			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
oil tank #2 developed a hole in the bottom - called vacuum truck to recover what we could - pulled tank out of service

Describe Area Affected and Cleanup Action Taken.*
Tetra Tech personnel inspected the site and collected samples to define the spills extent. Since depth to water was unknown in the area of the spill, Tetra Tech installed a Temporary Monitor Well and determined the depth to groundwater to be greater than 100 feet below surface. Tetra Tech prepared a closure report and submitted it to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez	Approved by District Supervisor:	Accepted for record NMOCD 5/11/15
Title: Senior Project Manager	Approval Date:	Expiration Date:
E-mail Address: ike.tavarez@tetrattech.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/30/2013 Phone: 432-682-4559	Clean-up deferred until site abandonment	

Attach Additional Sheets If Necessary