## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

David Martin Cabinet Secretary

**Tony Delfin** Deputy Cabinet Secretary David Catanach, Director Oil Conservation Division



## \*Response Required - Deadline Enclosed\*

Field Inspection Program "Preserving the Integrity of Our Environment"

05-Jul-16

## ALAMO PERMIAN RESOURCES, LLC

415 W. WALL STREET, SUITE 500 MIDLAND TX 79701

## **LETTER OF VIOLATION - Inspection**

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

		INSPECTIO	N DETAIL	SECTION		
SMITH STATE No.001 Inspection Date Type Inspection		Inspector	Violation?	A-4-18S-28E *Significant Non-Compliance?	30-015-02556-00-00 Corrective Action Due By: Inspection No	
07/05/2016	Routine/Periodic Violations General Housekeeping (Rule	Tony Morales	Yes	No	10/8/2016	iTM1618741585
Comments		quipment and Location in ATTERIES NO CONTAIN		. PJO. STAINING A	ROUND WELL HEA	\D
SOLT STA' Inspection Date	TE No.002 Type Inspection	Inspector	Violation?	P-5-18S-28E *Significant Non-Compliance?	30-015-25278-00- Corrective Action Due By:	00 Inspection No.
07/05/2016	Routine/Periodic Violations General Housekceping (Rule	Tony Morales	Yes	No	10/8/2016	iTM1618750035
Comments		equipment and Location ir	a Good Shape	. PJO. TANK BAT	FTERIES OK. OLD T	ANK

SOLT STAT	ГЕ No.003			O-5-18S-28E	30-015-25390-00-0	00
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/05/2016	Routine/Periodic Violations General Housekeeping (Rule	Tony Morales	Yes	No	10/8/2016	iTM1618750503
Comments		Equipment and Location ir	n Good Shape	. PJ CONTAMIN	ATED MATERIAL N	EXT
FEATHERS Inspection Date	STONE STATE B No.00 Type Inspection	)5 Inspector	Violation?	K-2-18S-28E *Significant Non-Compliance?	30-015-39591-00-0 Corrective Action Due By:	)() Inspection No.
07/05/2016	Routine/Periodic Violations General Housekeeping (Rule	Tony Morales	Yes	No	10/8/2016	iTM1618730467
Comments	on Inspection: OK. All E	quipment and Location ir 11NATED MATERIAL O	•		ROUND WELL HEA	D
FEATHERS Inspection Date	STONE STATE E No.00 Type Inspection	)6 Inspector	Violation?	F-2-18S-28E *Significant Non-Compliance?	30-015-39592-00-0 Corrective Action Due By:	00 Inspection No.
07/05/2016	Routine/Periodic Violations General Housekeeping (Rule	Tony Morales	Yes	No	10/8/2016	iTM1618732900
Comments	on Inspection: OK. All E	Equipment and Location ir O AREA APPROX. 10' X				•

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. \*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.