State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

David Martin Cabinet Secretary

Tony Delfin Deputy Cabinet Secretary David Catanach, Director Oil Conservation Division



Response Required - Deadline Enclosed

Field Inspection Program "Preserving the Integrity of Our Environment"

05-Jul-16

BREITBURN OPERATING LP

1401 MCKINNEY STREET SUITE 2400 HOUSTON TX 77010

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

		INSPECTIO	N DETAIL	SECTION		
ARTESIA U Inspection Date	UNIT No.045 Type Inspection	Inspector	Violation?	F-3-18S-28E *Significant Non-Compliance?	30-015-01775-00- Corrective Action Due By:	00 Inspection No.
07/05/2016	Routine/Periodic Violations Absent Well Identification Si General Housekceping (Rule		Yes	No	10/8/2016	iTM1618742156
	-	quipment and Location ir AND OLD 55 GALLON			SIGN NOT VISIBLE	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/05/2016	Routine/Periodic Violations Absent Well Identification Si	Tony Morales gns (Rule 103)	Yes	No	10/8/2016	iTM1618735339
Comments	on Inspection: OK. All E	quipment and Location ir	n Good Shape	. LOCATION SIGN	NOT VISIBLE 19.15	.16.8

ARTESIA UNIT No.064 Inspection					N-2-18S-28E 30-015-01784-00-00			
Date	Type Inspection	I.	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
07/05/2016	Routine/Perio Violations	dic	Tony Morales	Yes	No	10/8/2016	iTM1618734244	
	General Houseke	eping (Rule 114)						
Comments	on Inspection:	OK. All Equipm	ent and Location in A APPROX 5' X 1		PJ. STAINING ARC	OUND WELL HEAD		
ARTESIA U	JNIT No.043				E-3-18S-28E	30-015-01790-00-0	0	
Inspection Date	Type Inspection		Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
07/05/2016	Routine/Perio Violations	dic	Tony Morales	Yes	No	10/8/2016	iTM1618740651	
	Absent Well Iden	tification Signs (Ru	ile 103)					
Comments	on Inspection:	OK. All Equipm 19.15.16.8	ent and Location in	n Good Shape.	PJ. LOCATION	SIGN NOT VISIBLE F	ULE	
ARTESIA UNIT No.059				-	M-3-18S-28E	30-015-01792-00-0	0	
Inspection Date	Type Inspection		Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
07/05/2016	Routine/Perio		Tony Morales	Yes	No	10/8/2016	iTM1618744054	
	Absent Well Iden	tification Signs (Ru	ile 103)					
Comments of	on Inspection:	OK. All Equipm	ent and Location in	n Good Shape.	LOCATION NOT	ISIBLE.		
ARTESIA U	UNIT No.055				K-3-18S-28E	30-015-01798-00-0	0	
Inspection Date	Type Inspection	I	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
07/05/2016	Routine/Perio Violations		Tony Morales	Yes	No	10/8/2016	iTM1618742550	
Comments	General Housekeeping (Rule 114) n Inspection: OK. All Equipment and Location in Good Shap			n Cood Shane	PJ. POWER OFF. OLD 55 GALLON DRUM			
		ON LOCATION		n Oood Shape.				
ARTESIA UNIT No.042					D-3-18S-28E	30-015-02547-00-00		
Inspection Date	Type Inspectior	l	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
07/05/2016	Routine/Perio Violations General Houseke		Tony Morales	Yes	No	10/8/2016	iTM1618740983	
General Housekeeping (Rule 114) Comments on Inspection: OK. All Equipment and Location in DEBRIS ON LOCATION			n Good Shape.	. PJO. CONTAMI	NATED MATERIAL			
ARTESIA U	UNIT No.065				G-3-18S-28E	30-015-20273-00-0	0	
Inspection Date	Type Inspection	1	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
07/05/2016	Routine/Perio Violations		Tony Morales	Yes	No	10/8/2016	iTM1618738328	
		tification Signs (R						
Comments	on Inspection:	OK. All Equipn 19.15.16.8	ent and Location i	n Good Shape	. LOCATION SIGN	NOT VISIBLE. RULE		

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown_above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.