Submit One Copy To Appropriate District	State of New Mexico		Form C-103
Office District 1	Energy, Minerals and Natural Resources		Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-015-27008
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			USA CACTUS 16 STATE
1. Type of Well: Oil Well Gas Well Other: Injection			8. Well Number #001
Name of Operator CHEVRON USA INC	ame of Operator		9. OGRID Number
3. Address of Operator			4323 10. Pool name or Wildcat
<u>-</u>		To Too hallo of Wilden	
15 SMITH ROAD, MIDLAND, TEXAS 79705			
4. Well Location Unit Letter C: 330 feet from the NORTH line and 2310 feet from the WEST line			
			feet from the WEST line NMPM County EDDY
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3492			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INT	ENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			_
	CHANGE PLANS	LLING OPNS. P AND A	
PULL OR ALTER CASING OTHER:	MULTIPLE COMPL	CASING/CEMENT	T JOB 🔲
✓ Location is ready for OCD inspection after P&A			
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the following:			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT			
LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY			
STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other			
production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least the below ground level. If this is a one-well lease or last remaining well on lease, the ball that and pit location(s) have been remediated in compliance with OCD rules			
and the terms of the Operator's pit permit and closure plan. Alt the operator's pit permit and closure plan. Alt the operator of the Operator's pit permit and closure plan.			
location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be			
removed.)			
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow			
lines and pipelines.			
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed that lease and well location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
	→		
SIGNATURE:	TITLE: _	Project Rep	DATE: 5-24-16
TYPE OR PRINT NAME Chris Gibbo For State Use Only	ns E-MAIL: egibbo	ons@chevron.com	PHONE: 985-228-0582
BY: Matet 2 Knl	TITLE COMPL	imile OFF	9188 7/15/2016