Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR FISHED OF BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELL AFTERIA NO. NMNM36975

Do not use thi	s form for proposals to drill (or to re-enter an			
abandoned we	6. If Indian, All	6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRI	7. If Unit or CA	/Agreement, Name and/or No.			
1. Type of Well				Well Name and No. MultipleSee Attached	
☑ Oil Well ☐ Gas Well ☐ Other					
2. Name of Operator FASKEN OIL & RANCH LIMIT	Contact: JACK FED E-Mail: jlathan@mewbou	9. API Well No. MultipleSee Attached			
3a. Address 6101 HOLIDAY HILL ROAD MIDLAND, TX 79707	Phone No. (include area code) 575-393-5905	10. Field and Po WILLOW I	10. Field and Pool, or Exploratory WILLOW LAKE-BONE SPRING, SE		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, and State		
MultipleSee Attached			EDDY CO	EDDY COUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO INC	DICATE NATURE OF I	NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION .				
D Notice of leaves	☐ Acidize	☐ Deepen	☐ Production (Start/Resur	ne) Water Shut-Off	
■ Notice of Intent	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	■ Well Integrity	
☐ Subsequent Report	Casing Repair	■ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	Change Plans	Plug and Abandon	□ Temporarily Abandon		
· .	Convert to Injection	☐ Plug Back	■ Water Disposal		
determined that the site is ready for for Mewbourne Oil Company is ready for form Attached is the change of open Please contact Robin Terrell vibration on file: NM1693 nationw	equesting a 1 year evaluation parator form that was submitted (with any questions.		•	OIL CONSERVATION ARTESIA DISTRICT JUL 1 9 2016 RECEIVED	
		Accep	ted For Record	! 	
14. I hereby certify that the foregoing is Com Name (Printed/Typed) ROBIN TE	Electronic Submission #34408 For FASKEN OIL & R nmitted to AFMSS for processing	ANCH LIMITED, sent to t by PRISCILLA PEREZ o	Il Information System	,	
Signature (Electronic S	Submission)	. Date 07/07/2	016		
	THIS SPACE FOR FI	EDERAL OR STATE	OFFICE USE		
Approved By DUNCAN WHITLOG	TitleTECHNIC.	AL LPET	Date 07/07/2016		
Conditions of approval, if any, are attached ertify that the applicant holds legal or equivalent would entitle the applicant to conduction.	arrant or				
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime tatements or representations as to any	for any person knowingly and matter within its jurisdiction.	willfully to make to any departn	nent or agency of the United	

Additional data for EC transaction #344082 that would not fit on the form

Wells/Facilities, continued

Agreement Lease . NMNM36975 NMNM36975 NMNM36975 NMNM36975

Well/Fac Name, Number 75 SALT DRAW 28 FEDERAL 1 75 SALT DRAW 28 FEDERAL 1 **API Number** 30-015-26142-00-S1 30-015-26142-00-S2

LocationSec 28 T24S R28E SENE 1980FNL 660FEL
Sec 28 T24S R28E SENE 1980FNL 660FEL



United States Department of the Interior BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St.



Carlsbad, New Mexico 88220 Tel. (505) 234-597 Fax (505) 234-5927

TA of Well on Federal Lands Conditions of Approval

Mewbourne Oil Company Salt Draw 28 Federal 1

3001526142, 36975

As per your Sundry request the above well is Temporary Abandoned (TA). A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer. 43 CFR 3162.3-4 (C) requires that wells incapable of production in paying quantities be promptly plugged and abandoned and requires approval for any well temporarily abandoned for more than 30 days.

Your Sundry Notice is being APPROVED.

Approved for 12 month period ending 7/7/2017

Return the well to production or Submit Notice of Intent to P&A by 7/7/2017. This will be the last approval to TA this well. The last oil production for this well was 4/2013. Last MIT done on this well was 12/17/2014

43 CFR 3162.4-1(c) also requires you to notify the Authorized officer, not later than the fifth business day after production is resumed for any well which has been off production for more than 90 days, the date on which such production was resumed. Submit Sundry Notice within 5 days of well-being placed back on production.

JDW 7/7/16