

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

JUL 19 2016 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: FIREFOX 4 FEDERAL COM #005H	Facility Type:

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-41423
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	4	19S	31E	670	South	250	West	Eddy

Latitude Longitude

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 20 bbls Oil ; 5 bbls PW	Volume Recovered: 15 bbls Oil ; 3 bbls PW
Source of Release: Heater treater	Date and Hour of Occurrence: 7/11/2016 unknown	Date and Hour of Discovery: 7/11/2016 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Shelly Tucker - BLM	
By Whom? Amanda T. Davis	Date and Hour: 7/11/2016 6:21 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a hole in the heater treater. A vacuum truck was dispatched to recover free liquids and Microblaze was applied to the pasture areas.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred primarily in the containment however a spray of fluids impacted the nearby pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amanda T. Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: 7/21/16	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: <input checked="" type="checkbox"/> Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: July 19, 2016	Phone: 575-748-6940	

\* Attach Additional Sheets If Necessary

LATER THAN: 8/25/16

ARP-3789