

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUL 29 2016

Form C-14  
Revised August 8, 201

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

RECEIVED

## Release Notification and Corrective Action

NAB1621454089

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	WILLOW 17 STATE SWD #001	Facility Type:	Tank Battery
Surface Owner:	State	Mineral Owner:	API No. 30-015-41806

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	17	25S	28E	660'	South	660'	East	Eddy

Latitude 32.1243935 Longitude 104.1029892

## NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	80bbls of Produced Water	Volume Recovered:	0bbls Produced Water
Source of Release:	Hose connecting to the load line	Date and Hour of Occurrence:	07-24-2016 08:00am	Date and Hour of Discovery:	07-24-2016 08:00am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Robert Grubbs Jr.	Date and Hour: 7/25/2016 9:28 AM			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A truck was unloading when his hose disconnected from the load line. Make sure that hose connect is secure before unloading.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred when hose connection failed going to a load line on the pad. A 5X5 area went off in the pasture next to the location. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist:	
Title:	Senior Environmental Coordinator	Approval Date:	8/2/16
E-mail Address:	rgrubbs@concho.com	Expiration Date:	N/A
Date:	July 28, 2016	Phone:	432-683-7443
		Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN:

9/2/16

2RP-3812