District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

NM OIL CONSERVATION ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

AUG 1/4 2016 Submit I Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action													
nAB1421834453						OPERATOR			☑ Initial Report ☐ Fina			Final Report	
Name of Company: COG Operating LLC 22913						/Contact:			Robert McNeill				
Address: 600 West Illinois Avenue, Midland TX 79701						Telephone No.			432-683-7443				
Facility Name: CLUSTER STATE COM #001H						Facility Type:			Flowline				
Surface Owner: State Mineral Owner					wner:				API No.	30-0	15-375	47	
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the					West Line		County		
D	16	26S	27E	380'	1	North	330.		West		Eddy		
Latitude 32.0486679 Longitude 104.2026672 NATURE OF RELEASE													
Type of Rele	ase:	Volume of	e of Release:			Volume Recovered:							
C	·		10bbls of Produced Water			Obbls of Produced Water Date and Hour of Discovery:							
Source of Release: Flowline						Date and Hour of Occurrence: 08/03/2016 10:30 am			08/03/2016 10:30 am				
Was Immediate Notice Given? If YES, To Whom?													
		U	Yes 🗵	No 🛭 Not R	equired								
By Whom? Was a Water	course Bas	Date and Hour: If YES, Volume Impacting the Watercourse.											
was a water	conise Ren	•	It 1 Ed, volume impacing the watercourse.										
If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* A polyline was damaged by a vehicle or road equipment. Replaced damaged section of line.													
Describe Are	a Affected	and Cleanup /	Action Tal	ten.*									
Describe Area Affected and Cleanup Action Taken.* This release occurred on a 4" polyline on the side of the road. A spill area of 200'X1'. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.													
regulations a public health should their or the enviro	il operators or the envi operations in nment. In	are required to ironment. The have failed to	o report as acceptant idequately OCD accep	nd/or file certain ce of a C-141 rep investigate and	release n ort by the remediat	otifications a e NMOCD m e contaminat	knowledge and to nd perform correct arked as "Final Roon that pose a the on that pose a the e the operator of	ctive act Report" (reat to g	tions for rele does not reli round water	ases which eve the ope , surface w	may en rator of ater, hu	idanger Tiability man health	
Simulation of the state of the							OIL CONSERVATION DIVISION						
Signature: Printed Nam	e;		t Grubbs	r.		Approved by	Environmental S	Specialio	the	6/	/		
Title:		Senior Environ	mental Co	· · · · · · · · · · · · · · · · · · ·		Approval Da	الداءاء)	Expiration	Date: N	/A		
E-mail Addr	-	rgrubbs@	concho.c			Conditions o		.D. Ru	les & Gui	Attache i delines			

LATER THAN:_