

NM OIL CONSERVATION

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 12 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB11022832817

Name of Company Oxy Permian Ltd. <i>110696</i>		Contact Casey Summers	
Address 6 Desta Drive, Midland, TX 79705		Telephone No. (575) 513-8289	
Facility Name SDS 11 Federal #1 SWD		Facility Type SWD	
Surface Owner BLM		Mineral Owner	
		API No. 30-015-27627	

OPERATOR

☒ Initial Report ☐ Final Report

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	11	24S	31E					Eddy

Latitude N 32.23328° Longitude W 103.75060°

NATURE OF RELEASE

Type of Release Oil	Volume of Release 10 bbls	Volume Recovered 10 bbls
Source of Release Gun barrel surge	Date and Hour of Occurrence 08/08/16	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM	
By Whom? Kathy Purvis @ BBC International Inc.	Date and Hour 08/09/2016 @ 12:04 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A gun barrel surge caused 10 bbls of oil to leak inside the lined containment on location. A vacuum truck recovered all free-standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 80' x 4' inside the lined containment on location. Remediation will be completed by removing the contaminated material and replacing it with clean material.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>[Signature]</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Casey Summers	Approval Date: <i>8/15/16</i> Expiration Date: <i>N/A</i>	
Title: NM Environmental Advisor	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
E-mail Address: Casey_Summers@oxy.com	SUBMIT REMEDIATION PROPOSAL NO	
Date: <i>8-12-16</i> Phone: (575) 513-8289		

* Attach Additional Sheets If Necessary

LATER THAN: *8/15/16*

2RP-3831