
State of New Mexico
Energy, Miner Vatural Resources Department



Inspection Date: 7/13/2016 9:41:53 AM Corrective Action Due by: 10/16/2016 Violation? *Significant Non-Compliance? Type Inspection Inspector Routine/Periodic Tony Morales Yes No Comments on Inspection: Idle Well (Rule 201) NO PL. CASING OUT OF GROUND LOCATION SIGN NOT VISIBLE. CONTAMINATED MATERIAL ON LOCATION ARTESIA METEX UNIT 021 M-19-18S-28E 30-015-01942-00-00 Inspection No. iTM1619533198 Corrective Action Due by: 10/16/2016 Inspection Date: 7/13/2016 9:13:15 AM Type Inspection Inspector Violation? *Significant Non-Compliance? Routine/Periodic Tony Morales Yes No Comments on Inspection: NO PJ. CASING OUT OF GROUND Idle Well (Rule 201) LOCATION SIGN NOT VISIBLE. ARTESIA METEX UNIT 010 L-19-18S-28E Inspection No. iTM1619533964 30-015-01943-00-00 Corrective Action Due by: 10/16/2016 7/13/2016 9:26:02 AM Inspection Date: Violation? *Significant Non-Compliance? Type Inspection Inspector Routine/Periodic Tony Morales Yes Comments on Inspection: NO PJ. CASING OUT OF GROUND Idle Well (Rule 201) LOCATION SIGN NOT VISIBLE. O-19-18S-28E Inspection No. iTM1619535680 **ARTESIA METEX UNIT 025** 30-015-01946-00-00 Corrective Action Due by: 10/16/2016 **Inspection Date:** 7/13/2016 9:54:37 AM Violation? *Significant Non-Compliance? Type Inspection Inspector Routine/Periodic Yes No Tony Morales NO PJ. CASING OUT OF GROUND Comments on Inspection: Idle Well (Rule 201) LOCATION SIGN NOT VISIBLE. 30-015-01947-00-00 Inspection No. iTM1619536694 ARTESIA METEX UNIT 014 J-19-18S-28E Corrective Action Due by: 10/16/2016 7/13/2016 10:11:31 AM Inspection Date: Type Inspection Inspector Violation? *Significant Non-Compliance? Routine/Periodic Yes No Tony Morales NO PJ. CASING OUT OF GROUND Comments on Inspection: Idle Well (Rule 201) LOCATION SIGN NOT VISIBLE. Inspection No. iTM1619535377 ARTESIA METEX O-19-18S-28E 30-015-01949-00-00 **UNIT** 024 Corrective Action Due by: 10/16/2016 Inspection Date: 7/13/2016 9:49:36 AM Violation? *Significant Non-Compliance? Type Inspection Inspector Routine/Periodic **Tony Morales** Yes No Comments on Inspection: Idle Well (Rule 201) NO PJ. CASING OUT OF GROUND LOCATION ARTESIA METEX UNIT 013 J-19-18S-28E 30-015-01951-00-00 Inspection No. iTM1619532178 Inspection Date: Corrective Action Due by: 10/16/2016 7/13/2016 8:56:16 AM Violation? *Significant Non-Compliance? Type Inspection Inspector Routine/Periodic **Tony Morales** Yes No Comments on Inspection: Idle Well (Rule 201) NO PJ. CASING OUT OF GROUND LOCATION SIGN NOT VISIBLE. ARTESIA METEX UNIT 015 I-19-18S-28E 30-015-01954-00-00 Inspection No. iTM1619536207 Corrective Action Due by: 10/16/2016 Inspection Date: 7/13/2016 10:03:24 AM Type Inspection Violation? *Significant Non-Compliance? Inspector Routine/Periodic Yes **Tony Morales** No Comments on Inspection: Idle Well (Rule 201) NO PJ. CASING OUT OF GROUND LOCATION SIGN NOT VISIBLE. ARTESIA METEX UNIT 012 K-19-18S-28E 30-015-01964-00-00 Inspection No. iTM1619532435

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely,

Artesia OCD District Office

* Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas.