

Inspection Date: 7/13/201	6 9:41:53 AM	Corrective Action Due by: 10/16/2016	
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales	Yes	No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VI	NO I SIBLE, CONTAMINATED MA	2J. CASING OUT OF GROUND ATERIAL ON LOCATION
RTESIA METEX UNIT 02	1 M-19-18S-28E	30-015-01942-00-00	Inspection No. iTM1619533198
Inspection Date: 7/13/201	6 9:13:15 AM	Correctiv	e Action Due by: 10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales	Yes	No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VI		PJ. CASING OUT OF GROUND
RTESIA METEX UNIT 01	0 L-19-18S-28E	30-015-01943-00-00	Inspection No. iTM1619533964
Inspection Date: 7/13/201	6 9:26:02 AM	Correctiv	ve Action Due by: 10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales	Yes	No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VI		PJ. CASING OUT OF GROUND
RTESIA METEX UNIT 02	5 O-19-18S-28E	30-015-01946-00-00	Inspection No. iTM1619535680
Inspection Date: 7/13/201	6 9:54:37 AM	Correcti	ve Action Due by: 10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales	Yes	No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VI		PJ. CASING OUT OF GROUND
RTESIA METEX UNIT 01	4 J-19-18S-28E	30-015-01947-00-00	Inspection No. iTM1619536694
Inspection Date: 7/13/201	6 10:11:31 AM	Correcti	ve Action Due by: 10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales		No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VI		PJ. CASING OUT OF GROUND
ARTESIA METEX	O-19-18S-28E	30-015-01949-00-00	Inspection No. iTM1619535377
NIT 024			
Inspection Date: 7/13/201	16 9:49:36 AM	Correcti	ve Action Due by: 10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales		No
Comments on Inspection:	ldie Well (Rule 201) LOCATION	NO	PJ. CASING OUT OF GROUND
ARTESIA METEX UNIT 01	J-19-18S-28E	30-015-01951-00-00	Inspection No. iTM1619532178
Inspection Date: 7/13/20	16 8:56:16 AM	Correcti	ve Action Due by: 10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales		No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VI		PJ. CASING OUT OF GROUND
RTESIA METEX UNIT 01	I5 I-19-18S-28E	30-015-01954-00-00	Inspection No. iTM1619536207
Inspection Date: 7/13/20	16 10:03:24 AM	Correcti	ve Action Due by: 10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales		No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VI		PJ. CASING OUT OF GROUND
	LOCATION DIGIT NOT VI		

Oil Conservation Division * 811 S. First St. * Artesia, New Mexico 88210 Phone: 575-748-1283 * Fax: 575-748-9720 * http://www.ennrd.state.nm.us Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely, Artesia OCD District Office

* Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas.

លោក ្រទោះ សារ សារ

م الديانية في إمدة كالتجاويرية الله الم

19、14(12)-154、1-22月3月16(11)154(11)154(11)154(11)154(11)154(11)154(11)154(11)154(11)154(11)154(11)154(11)154(11

Oil Conservation Division * 811 S. First St. * Artesia, New Mexico 88210 Phone: 575-748-1283 * Fax: 575-748-9720 * http://www.emnrd.state.nm.us