



LINN ENERGY, LLC.

NM OIL CONSERVATION
ARTESIA DISTRICT

600 Travis Street, Suite 5100
Houston, Texas 77002
Phone: (281) 840-4000
Fax: (281) 840-4001

AUG 26 2016

August 23, 2016

RECEIVED

State of New Mexico
Oil Conservation Division
811 S. First St.
Artesia, New Mexico 88210

Re: WELCH No. 001
30-015-25306-00-00
Inspection No. ITM1620233085


Dear Mr. Morales:

In response to your Letter of Violation dated July 20, 2016, Linn Operating, Inc. respectfully submits photos as evidence that the Welch No. 001 location has been cleaned of all debris per General Housekeeping (Rule 114) as referenced in your notice.


If you have any questions or require additional information please contact Debra Gordon at 281.840.4010 or by e-mail at dgordon@linnenergy.com.

Sincerely,


LINN OPERATING, INC.


Nancy Fitzwater
Regulatory Supervisor

Attachment




WELCH No. 001
Inspection No. ITM1620233085
Before Photo




WELCH No. 001
Inspection No. ITM1620233085
Before Photo




WELCH No. 001
Inspection No. ITM1620233085
Post Cleanup




WELCH No. 001
Inspection No. ITM1620233085
Post Cleanup




WELCH No. 001
Inspection No. ITM1620233085
Post Cleanup




WELCH No. 001
Inspection No. ITM1620233085
Post Cleanup



WELCH No. 001
Inspection No. ITM1620233085
Post Cleanup



WELCH No. 001
Inspection No. iTM1620233085
Post Cleanup



WELCH No. 001
Inspection No. iTM1620233085
Post Cleanup