

**NM OIL CONSERVATION**

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 06 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

**RECEIVED****Release Notification and Corrective Action****OPERATOR**☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU 55 Battery	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-27589
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter F	Section 17	Township 23S	Range 31E	Feet from the 2100	North/South Line North	Feet from the 1900	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.305973° Longitude -103.802098°**NATURE OF RELEASE**

Type of Release Crude Oil	Volume of Release 43 bbl	Volume Recovered 40 bbl
Source of Release Three Phase Vessel	Date and Hour of Occurrence 8/26/2016 time unknown	Date and Hour of Discovery 8/26/2016 10:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD), Shelly Tucker (BLM)	
By Whom? Amy Ruth	Date and Hour 8/26/2016 at 3:08 pm by email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
A gasket in the upper portion of the three phase vessel failed. The failed gasket material was replaced.

Describe Area Affected and Cleanup Action Taken.\*  
The leak affected 6,700 square feet of the caliche pad and misted 1,200 square feet of pasture area between the location and lease road to the south. Vacuum trucks recovered 40 bbl of standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amy C. Ruth</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy C. Ruth	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: EHS Remediation Specialist	Approval Date: <i>9/16/16</i>	Expiration Date: <i>NIA</i>
E-mail Address: ACRuth@basspet.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> Attached <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO</b>	
Date: 9/1/2016 Phone: 432-661-0571	<b>LATER THAN: <i>10/18/16</i></b>	

\* Attach Additional Sheets If Necessary

*2RP-3863*