District 1
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 NM OIL CONSERVATION
ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

SEP 0.7. 2016
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action												
NAB 1625327393						OPERATOR						
Name of Company: XTO Energy, Inc. 5380						Contact: Dudley McMinn						
Address: 50			Telephone No.: (432) 682-8873									
Facility Nar	ne: Nash	Draw Unit B	attery #3	6	facility Type: Tank Battery (Equipment Removed)							
Surface Owner: Federal Mineral Owner: Federal API No. 30-015-30176												
LOCATION OF RELEASE												
						South Line South	Feet from the 1585		Vest Line Vest	County: E	ddy	
Latitude 32.316944 Longitude103.941667												
NATURE OF RELEASE												
Type of Release: Crude Oil							Volume of Release: Unknown Volume Recovered: None					
Source of Release: Spills							Date and Hour of Occurrence Date and Hou Unknown 07-20-2016			Hour of Disc 16	covery	
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required							If YES, To Whom?					
By Whom?						Date and Hour						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.* Hydrocarbons in soil due to historic use of tank battery reported in soil samples by laboratory following removal of tanks and equipment. Will remediate to OCD and BLM requirements.												
Describe Area Affected and Cleanup Action Taken.* Affected soil to be excavated, treated onsite treatment or disposed offsite at OCD approved facility. Refer to attached analytical data summary.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
Signature:							OIL CONSERVATION DIVISION					
Printed Name: Luke Williams							Approved by Environmental Specialist:					
Title: EH&S Coordinator Approval Date: USIO Expiration Date: NA											A	
E-mail Addr	ess: Luke_V	Villiams@xto	energy.co	m	Conditions of Approval: Remediation per O.C.D. Rules & Guidalings							
Date: 09-07				one: (432) 683-88°	73	SUBMIT REMEDIATION PROPUSALING						
* Attach Addi	itional She	ets If Necess	ary		Ì	LATER T	HAN:	иШ	<i>P</i>	•	ZRP-387	