

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

SEP 19 2016  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

**OPERATOR** ☒ Initial Report ☐ Final Report

**Name of Company:** COG Operating LLC **Contact:** Robert McNeill  
**Address:** 600 West Illinois Avenue, Midland TX 79701 **Telephone No.** 432-683-7443  
**Facility Name:** HIGH BRASS #002H **Facility Type:** Tank Battery



**Surface Owner:** Private **Mineral Owner:** **API No.** 30-015-40865

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	20	24S	28E	330'	South	2256'	West	Eddy

Latitude 32.1969109 Longitude 104.1109009

NATURE OF RELEASE

Type of Release: Produce Water	Volume of Release: 7bbls	Volume Recovered: 6bbls
Source of Release: Gasket	Date and Hour of Occurrence: 09-17-2016 08:15 am	Date and Hour of Discovery: 09-17-2016 08:15 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*  A gasket failed on a heater treater failed due to high pressure. Lower the pressure and replace the gasket.		
Describe Area Affected and Cleanup Action Taken.*  The release was contained within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment will be cleaned and the facility will be put back into operation. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 9/19/16	Expiration Date: N/A
E-mail Address: rgrubbs@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: August 19, 2016	Phone: 432-683-7443	

\* Attach Additional Sheets If Necessary

LATER THAN: 10/20/16

2RD-3895