

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OCT 04 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
To appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1617853512 Name of Company Chevron USA 4323		OPERATOR		<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report	
Address 6301 Deauville Blvd, Midland, TX 79706		Contact Josepha DeLeon			
Facility Name Greenwood PGU #4 Battery		Telephone No. 575-263-0424			
		Facility Type Tank Battery			
Surface Owner BLM		Mineral Owner		API No. 30-015-05616	

LOCATION OF RELEASE

Unit Letter D	Section 27	Township 18S	Range 31E	Feet from the 600	North/South Line North	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude **N 32.720010** Longitude **-W 103.849308**

NATURE OF RELEASE

Type of Release: Oil		Volume of Release 227.30 bbls	Volume Recovered 165 bbls
Source of Release: Tank Bottom Failed		Date and Hour of Occurrence 09/05/2016 @ unknown	Date and Hour of Discovery 09/05/2016
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required		If YES, To Whom? Jaime Keyes, NMOCD Jim Amos, BLM	
By Whom? Josepha DeLeon		Date and Hour 09/05/2016	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* Not Applicable			
Describe Cause of Problem and Remedial Action Taken.* Leak from oil tank resulted in the release of contents to containment. A vacuum truck was dispatched to collect standing fluid.			
Describe Area Affected and Cleanup Action Taken.* Affected area included containment area with small adjacent area outside of the berm (~0.87 bbl of oil leaked outside of the berm). A vacuum truck was called to the location and recovered 165 barrels.			
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.			

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Josepha DeLeon		Approved by Environmental Specialist	
Title: HES Compliance Support - Environmental		Approval Date: 10/4/16	Expiration Date: N/A
E-mail Address: jdxd@chevron.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 09/20/2016 Phone: 575-263-0424		SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 11/4/16	

* Attach Additional Sheets If Necessary

2RP-3929