	NM OIL CONSERVATION ARTESIA DISTRICT
1625 N. French Dr., Hobbs, NM 88240	f New Mexico OCT 0 3 2016 Form C-141 s and Natural Resources Revised August 8, 2011
District III Oil Conse 1000 Rio Brazos Road, Aztec, NM 87410 1220 Sout District IV 1220 Sout	th St. Francis Dr.
Sana re, inizi o7303	
Release Notification and Corrective Action	
Name of Company: COG Operating LLC 229/37	OPERATOR Initial Report Final Report
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: BLUE THUNDER 4 FEDERAL #001	Facility Type: Battery
Surface Owner: Federal Mineral Owner	: Federal API No. 30-015-34125
LOCATION OF RELEASE	
Unit LetterSectionTownshipRangeFeet from theNorM0419S31E810	th/South Line Feet from the East/West Line County South 660 West Eddy
Latitude Longitude	
	E OF RELEASE
Type of Release: Oil	Volume of Release: Volume Recovered: 6 bbls Oil 0 bbls Oil
Source of Release: Tank Overflow	Date and Hour of Occurrence: Date and Hour of Discovery:
Was Immediate Notice Given?	9/23/2016 Unknown 9/23/2016 9:00 AM If YES, To Whom?
Yes No X Not Required	
By Whom? Was a Watercourse Reached?	Date and Hour: If YES, Volume Impacting the Watercourse.
Yes X No	n res, volume impacting the watercourse.
If a Watercourse was Impacted, Describe Fully.*	
Describe Cause of Problem and Remedial Action Taken.*	
This release was caused when the dump valve failed to close allowing of the dump line will be re-routed to a larger steel tank.	excess gas to transfer to the fiberglass tank. The dump valve is being replaced and
Describe Area Affected and Cleanup Action Taken.*	
This release remained within the dirt berm and on the location. The impacted areas of the location were scraped and the contaminated soils removed to	
eliminate further impact. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other	
federal, state, or local laws and/or regulations.	does not relieve the operator of responsibility for compliance with any other
	OIL CONSERVATION DIVISION
Signature: Dalos Nor	Signed By Mile Kar
Printed Name: Dakota Neel	Approved by Environmental Specialist:
Title: Environmental Coordinator	Approval Date: 101411(0 Expiration Date: N/A
E-mail Address: dneet2@concho.com	Conditions of Approval:
	Remediation per O.C.D. Rules & Guidelines
Date: October 3, 2016 Phone: 575-748-6933 * Attach Additional Sheets If Necessary	SUBMIT REMEDIATION PROPOSALINO
	ATER THAN: 114110 3RP-3431

. •