

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

OCT 03 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1627852804

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company:	COG Operating LLC 224137	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	WHITE OAK STATE #019	Facility Type:	Tank Battery

Surface Owner:	State	Mineral Owner:	API No.	30-015-37754
----------------	-------	----------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	23	17S	28E	990'	North	2275'	East	Eddy

Latitude 32.8252487 Longitude 104.1457443

NATURE OF RELEASE

Type of Release:	Oil & Produced Water	Volume of Release:	1bbl Oil & 9bbls Produced Water	Volume Recovered:	1bbl Oil & 8bbls Produced Water
Source of Release:	Produced Water Tank	Date and Hour of Occurrence:	09-30-2016 06:00 am	Date and Hour of Discovery:	09-30-2016 06:00 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour:				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Produced water tank overflowed due to the HOH being shut off for maintenance on the filter pot. Turn the HOH back on after service has been completed on equipment.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Signed By 	
Title:	Senior Environmental Coordinator	Approved by Environmental Specialist:	
E-mail Address:	rgrubbs@concho.com	Approval Date:	10/4/16
Date:	October 3, 2016	Expiration Date:	N/A
Phone:	432-683-7443	Conditions of Approval:	
		Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
		SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 11/4/16

2RP-3928