

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

OCT 13 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1628854271

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Cimax Energy	Contact Christine Alderman
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059
Facility Name Gadwall 18 Fed Com I	Facility Type production

Surface Owner Fed	Mineral Owner	API No. 30-015-33496
-------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	18	25S	27E	850	N	1490	W	Eddy

Latitude_32.13486_Longitude -104.23313

NATURE OF RELEASE

Type of Release crude oil	Volume of Release 200 bbls	Volume Recovered 70 bbls
Source of Release tank	Date and Hour of Occurrence 10/12/2016	Date and Hour of Discovery 10/12/2016
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker/Heather Patterson	
By Whom? Christine Alderman	Date and Hour 10/13/2016	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.

Describe Cause of Problem and Remedial Action Taken.

Tank developed corrosion hole. Fluid released into a lined, gravel filled containment.

Describe Area Affected and Cleanup Action Taken.

Once fluids were recovered it was noted that there was a hole in the liner, therefore 130 bbls were lost to the soils. We will delineate to determine depth of contamination.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Christine Alderman

Title: ESH Supervisor

E-mail Address: calderman@cimaxex.com

Date: 10/13/2016 Phone: 432-853-7059

OIL CONSERVATION DIVISION

Signed By: Mike Brandon
Approved by Environmental Specialist:

Approval Date: 10/14/16

Expiration Date: N/A

Conditions of Approval:

Remediation per O.C.D. Rules & Guidelines Attached ☐

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 11/14/16

* Attach Additional Sheets If Necessary

ARP-3939