

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

OCT 19 2016

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1029838248

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Oxy Permian Ltd. <i>1166916</i>	Contact	Casey Summers
Address	PO Box 4294, Houston, TX 77210	Telephone No.	(575) 513-8289
Facility Name	Riverbend Federal #005	Facility Type	Well
Surface Owner	BLM	Mineral Owner	API No. 30-015-27977

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	22	24S	29E					Eddy County, NM

Latitude N 32.20418° Longitude W 103.96664°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	65 bbls	Volume Recovered	50 bbls
Source of Release	Compromised water transfer line	Date and Hour of Occurrence	10/11/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy@ BBC International, Inc.	Date and Hour	10/12/2016 @ 4:38 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A compromised water transfer line leaked 65 bbls of produced water into the pasture north of location. A vacuum truck recovered 50 bbls of produced water and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 125' x 45' just north of location in the pasture. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION	
Signature:	Signed By <i>Mike Bratcher</i>
Printed Name: Casey Summers	Approved by Environmental Specialist:
Title: NM Environmental Advisor	Approval Date: <i>10/24/16</i> Expiration Date: <i>N/A</i>
E-mail Address: Casey_Summers@oxy.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>
Date: <i>10-19-16</i> Phone: (575) 513-8289	SUBMIT REMEDIATION PROPOSAL NO <i>220-3949</i>

* Attach Additional Sheets If Necessary

LATER THAN: *11/26/16*