

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

OCT 17 2016

Form C-141
Revised October 10, 2003

RECEIVED Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NAB1629541723



OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report	
Name of Company: Lime Rock Resources 227558	Contact: Michael Barrett
Address: P.O. Box 2147, Roswell, NM 88202	Telephone No.: 505.353.2644
Facility Name: Hawk 8 No. 46	Facility Type: Gas Line
Surface Owner: BLM	Mineral Owner State
Lease No. 30-015-28301	

LOCATION OF RELEASE

Unit Letter	Section 5	Township 18S	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.77049 Longitude -104.30511

NATURE OF RELEASE

Type of Release: mixed fluids	Volume of Release: 20 BBLs	Volume Recovered 0
Source of Release: gas line	Date and Hour of Occurrence 10/14/16	Date and Hour of Discovery 10/14/16 4pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 20 BBL	
If a Watercourse was Impacted, Describe Fully.* A dry water course, ravine/draw leading to the Pecos River was impacted. However no fluids reached the river.		
Describe Cause of Problem and Remedial Action Taken.* The line was immediately shut in. Talon/LPE was contracted to perform site assessment and sampling activities. A work plan will be generated and submitted to the NMOC and BLM for review.		
Describe Area Affected and Cleanup Action Taken.* The affected area was the draw only. Fluids migrated several hundred feet but did not reach the river. Oil absorbent booms will be placed in the event of rainfall. A sump will be constructed and the impacted portion of the draw will be flushed with fresh water to mitigate impacts as initial remedial actions. The water will be picked up with vac trucks and properly disposed of.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael Barrett	Approved by District Supervisor: 	
Title: Production Superintendent	Approval Date: 10/19/16	Expiration Date: N/A
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 10/17/2016 Phone: 505.353.2644	SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: 11/26/16

22-3945

* Attach Additional Sheets If Necessary