

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

OCT 17 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1629542376		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Oxy Permian Ltd.		Contact Casey Summers			
Address PO Box 4294, Houston, TX 77210		Telephone No. (575) 513-8289			
Facility Name FNR 26 Federal #1 CTB		Facility Type Battery			
Surface Owner BLM		Mineral Owner		API No. 30-015-30412	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	26	23S	30E					Eddy County, NM

Latitude N 32.26969° Longitude W 103.85422°

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 10 bbls	Volume Recovered 0 bbls
Source of Release Compromised 3" poly water transfer line	Date and Hour of Occurrence 10/03/2016	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Heather Patterson-NMOCD, Shelly Tucker-BLM	
By Whom? Kathy Purvis @ BBC International Inc.	Date and Hour 10/03/2016 @ 4:34 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A compromised 3" poly water transfer line spilled 10 bbls of produced water off location. No fluids were recovered and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 25' x 25' approximately 700 feet east of location. Remediation will be completed according to a remediation plan approved by both the BLM and NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Casey Summers		Approved by Environmental Specialist: 	
Title: NM Environmental Advisor		Approval Date: 10/19/16	Expiration Date: N/A
E-mail Address: casey_summers@oxy.com		Conditions of Approval:	
Date: 10-17-16 Phone: (575) 513-8289		Remediation per O.C.D. Rules & Guidelines	
		Attached <input type="checkbox"/>	
		SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 11/20/16

240-3946