

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

OCT 21 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

NAB 1629852113

Name of Company: BOPCO, L.P.	<i>260737</i>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329
Facility Name: Hudson 1 Federal well #7		Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31513
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	1	23S	30E	1500	North	1800	West	Eddy

Latitude 32.337062° Longitude -103.837058°

NATURE OF RELEASE

Type of Release	Crude Oil and Produced Water	Volume of Release	2 bbls Oil 8 bbls PW	Volume Recovered	2 bbls PW
Source of Release	Poly flow line	Date and Hour of Occurrence	10/6/2016 time unknown	Date and Hour of Discovery	10/6/2016 approx. 10 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	N/A	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.*	N/A				

Describe Cause of Problem and Remedial Action Taken.*
Poly flow line from well ruptured in area of pasture. Pumping unit was shut down and valves were closed for repairs.

Describe Area Affected and Cleanup Action Taken.*
The leak affected approximately 8,170 square feet of pasture (most of area misted) located north of the well. Free standing fluids were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION	
Printed Name: Amy C. Ruth		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: EHS Remediation Specialist		Approval Date: 10/24/16	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	
Date: 10/21/2016 Phone: 432-661-0571		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

LATER THAN: 11/26/16

280-3955