

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCT 21 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

7AB1629852573 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Amy Ruth	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: Hudson Federal Battery #1 (at Hudson Federal well #7)	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31513

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	1	23S	30E	2000	North	1875	West	Eddy

Latitude 32.335761° Longitude -103.836860°



NATURE OF RELEASE

Type of Release	Crude oil and produced water	Volume of Release	9 bbls Oil 24 bbls PW	Volume Recovered	3 bbls Oil 12 bbls PW
Source of Release	Ruptured Gasket	Date and Hour of Occurrence	10/3/2016 time unknown	Date and Hour of Discovery	10/3/2016 approx. 10 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson		
By Whom?	Amy Ruth	Date and Hour	10/3/2016 4:46 pm by email		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					

Describe Cause of Problem and Remedial Action Taken.*
Release of fluids was the result of a ruptured gasket on a gas supply pot. The vessel was isolated for repairs.

Describe Area Affected and Cleanup Action Taken.*
Leak affected approximately 5,000 square feet of misted pasture area west of the battery and 3670 square feet of caliche pad and earthen containment. Free standing fluids within the earthen containment were recovered via vacuum truck and Micro-Blaze was applied to the pasture area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy C. Ruth	Approved by Environmental Specialist: 	
Title: EHS Remediation Specialist	Approval Date: 10/24/16	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: 10/21/2016 Phone: 432-661-0571	LATER THAN: 11/26/16	

* Attach Additional Sheets If Necessary

2RP-3956