

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

OCT 24 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1629936433

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Apache Corporation 873	Contact Bruce Baker	
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982	
Facility Name Red Lake K State # 1 Battery	Facility Type: Battery	
Surface Owner State	Mineral Owner	API No. 30-015-33740

LOCATION OF RELEASE

Unit Letter K	Section 28	Township 17S	Range 28E	Feet from the 1650	North/South Line FSL	Feet from the 1650	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude N32.8027039 Longitude W104.1840439

NATURE OF RELEASE

Type of Release: Oil	Volume of Release 45 barrels of Oil	Volume Recovered 42 barrels of Oil
Source of Release: Circulating line	Date and Hour of Occurrence 10/10/2016	Date and Hour of Discovery 10/10/2016
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (NMOCD)	
By Whom? Bruce Baker	Date and Hour 10/11/2016 via phone and email at 3:09 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A release occurred due to pin hole developed in the steel circulating tank. The oil tank was isolated and vacuum truck was dispatched to pick-up standing oil. The line was replaced.

Describe Area Affected and Cleanup Action Taken.\* The majority of the release affected the pasture south of the battery.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Bruce Baker	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Approved by Environmental Specialist: H2	
Title: Environmental Technician	Approval Date: 10/25/16	Expiration Date: N/A
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval:	
Date: 10/24/2016 Phone: (432) 631-6982	Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 11/26/16	

\* Attach Additional Sheets If Necessary

2RP-39600