Form 3160-5 / (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Lease Serial No. STATE

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

6 If Indian Allottee or Tribe Name

abandoned well. Use form 3160-3 (APD) for such proposals.						
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.	
Type of Well Gas Well □ Otl			8. Well Name and No. NASH UNIT 1			
Name of Operator XTO ENERGY INCORPORA	RIAS		9. API Well No. 30-015-21277-00-S3			
3a. Address 500 W ILLINOIS STREET SU MIDLAND, TX 79701	o. (include area code 20-4318 8-3530	:) .	10. Field and Pool, or Exploratory NASH DRAW-DELAWARE/BS (AVALO			
4. Location of Well (Footage, Sec., T			11. County or Parish, and State			
Sec 13 T23S R29E SENE 198		EDDY COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO	D INDICATI	E NATURE OF	NOTICÉ, RE	EPORT, OR OTHER	RDATA
TYPE OF SUBMISSION	TYPE OF ACTION					
C) Notice of the	☐ Acidize	☐ Dec	pen	☐ Producti	on (Start/Resume)	☐ Water Shut-Off
☐ Notice of Intent	☐ Alter Casing ☐ Fr		ture Treat		ition	☐ Well Integrity
Subsequent Report	☐ Casing Repair	☐ Nev	v Construction	☐ Recomp	lete	Other
☐ Final Abandonment Notice	☐ Change Plans	☐ Plu	g and Abandon	☐ Tempora	nrily Abandon	Venting and/or Flari ng
	☐ Convert to Injection	. Plu	g Back	■ Water Disposal		•
ASSOCIATED WELLS: A REJECTED NASH UNIT #001 30-015-21277 NASH UNIT #005 20 015 21200 Notice With			! Please Resubmit The Sundry ! The Volumes Flared During Hours Specified. NM OIL CONSERVATION ARTESIA DISTRICT OCT 1 9 2016 RECEIVED			
14. I hereby certify that the foregoing is	Electronic Submission #3	GY INCORPO	RATED, sent to t	he Carisbad		
Name (Printed/Typed) PATTY R	URIAS		Title REGUL	ATORY ANA	LYST	
Signature (Electronic S			Date 09/26/2			
	THIS SPACE FO	K FEDERA	LUKSIAIE	OFFICE US	· C	
Approved By REJECTED			/S/ DA	VID R	. GLASS	Date 09/29/2016
Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu	Office Carlsbad					
Title 18 U.S.C. Section 1001 and Title 43 U.S. States any false, fictitious or fraudulent s					te to any department or a	gency of the United

Additional data for EC transaction #352391 that would not fit on the form

7. If Unit or CA/Agreement, Name and No., continued

891014168B 891014168X

32. Additional remarks, continued

NASH UNIT #019 30-015-27590
NASH UNIT #020 30-015-27877
NASH UNIT #023 30-015-28272
NASH UNIT #024 30-015-28271
NASH UNIT #025 30-015-28271
NASH UNIT #035 30-015-28271
NASH UNIT #033H 30-015-32476
NASH UNIT #034H 30-015-30176
NASH UNIT #036H 30-015-39737
NASH UNIT #039H 30-015-37166
NASH UNIT #040H 30-015-37166
NASH UNIT #044H 30-015-37166
NASH UNIT #042H 30-015-37194
NASH UNIT #043H 30-015-42206
NASH UNIT #044H 30-015-37194
NASH UNIT #049H 30-015-38663
NASH UNIT #049H 30-015-38663
NASH UNIT #050H 30-015-38991
NASH UNIT #056H 30-015-38992
NASH UNIT #056H 30-015-38992
NASH UNIT #057H 30-015-39303
NASH UNIT #057H 30-015-39303

The unexpected malfunction of equipment maintained by 3RD PARTY GAS PURCHASER has caused emergency flaring from the NASH 42 TB of approximately 3500 mcf/day.

GAS PURCHASER CONTINUES TO HAVE AN ISSUE WITH THEIR COMPRESSOR, CAUSING XTO TO FLARE INTERMITTENTLY, MAX FLARING OF 3500 MCFD. PLEASE ACCEPT THIS AS NOTICE FOR APRIL - JUNE 2016.

The flared production was measured by a meter installed on the flare line. The total duration and volume of flaring for each flare incident (if intermittent) and the total duration and volume for each calendar month, as measured by the meter, is as follows:

APRIL: 4/13 3.84 HRS, 4/17 3.04 HRS, 4/21 3.12 HRS, 4/30 .84 HRS - ALL <24 HR HOUR FLARING MAY: 5/11 6 HRS, 5/23 2.52 HRS, 5/24 15.80 HRS, 5/25 15.80 HRS, 5/29 2.35 HRS - ALL <24 HOUR FLARING

JUNE: 6/18 1.74 HRS, 6/20 6.98 HRS, 6/24 2.26 HRS - ALL <24 HR FLARING