

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NOV 01 2016

Form C-141
Revised August 8, 2011

RECEIVED
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

0AB1630657394

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company:	COG Operating LLC 229137	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	SRO STATE COM #064H	Facility Type:	Tank Battery
Surface Owner:	State	Mineral Owner:	API No. 30-015-42130

LOCATION OF RELEASE

Unit Letter E	Section 10	Township 26S	Range 28E	Feet from the 2450'	North/South Line North	Feet from the 710'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.0576019 Longitude 104.0815811

NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	30bbls	Volume Recovered:	25bbls
Source of Release:	1/4 Nipple	Date and Hour of Occurrence:	10-28-2016 12:15 pm	Date and Hour of Discovery:	10-28-2016 12:15 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Amber Groves - SLO			
By Whom?	Robert Grubbs Jr.	Date and Hour:	Sat 10/29/2016 11:51 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a 1/4" nipple that broke off causing the spill. Replaced the 1/4 nipple with a new one.

Describe Area Affected and Cleanup Action Taken.*

This release occurred in the pasture an area of 8X50 against the tank batteries berm. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Signed By:	<i>Mike Bratcher</i>
Title:	Senior Environmental Coordinator	Approved by Environmental Specialist:	
E-mail Address:	rgubbs@concho.com	Approval Date:	11/1/16
Date:	November 1, 2016	Expiration Date:	N/A
Phone:	432-683-7443	Conditions of Approval:	→
		Attached	<input checked="" type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-3974