Form 3160-5	OPERATORS COPY
(August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR	FORM APPROVED: OMB NO. 1004-0135
BUREAU OF LAND MANAGEMENT	Expires: July 31, 2010 5. Lease Serial No.
SUNDRY NOTICES AND REPORTS ON W	ELLS NMNM0557371
Do not use this form for proposals to drill or to re abandoned well. Use form 3160-3 (APD) for such	proposals. 6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on re	verse side. 7. If Unit or CA/Agreement, Name and/or No.
Type of Well Gas Well	8. Well Name and No.
2. Name of Operator Contact: ISABEL HU APACHE CORPORATION E-Mail: Isabel.Hudson@apacher	DSON 9. API Well No. corp.com 30-015-32308-00-C1
3a. Address 303 VETERANS AIRPARK LANE SUITE 3000 MIDLAND, TX 79705 3b. Phone N Ph: 432-8	o. (include area code) 10. Field and Pool, or Exploratory RED LAKE
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, and State
Sec 1 T18S R27E NENW 430FNL 2310FWL	EDDY COUNTY, NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION
Notice of Intent ☐ Acidize ☐ Dec	epen Production (Start/Resume) Water Shut-Off
☐ Alter Casing ☐ Fra	cture Treat
	w Construction
i de la companya de	g and Abandon 🔯 Temporarily Abandon
	g Back Water Disposal
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)	
Apache would like to perform the following work: Please see attachments.	
	Accepted for record
•	NMOCD RI
•	11/17/16
SEE ATTACHED FOR	
CONDITIONS OF APPROVAL	
CONDITIONS OF ATTROVAL	
14. I hereby certify that the foregoing is true and correct. Electronic Submission #347036 verified by the BLM Well Information System For APACHE CORPORATION, sent to the Carlsbad	
Committed to AFMSS for processing by PRISCILLA PEREZ on 08/08/2016 (16PP1923SE)	
Name(Printed/Typed) ISABEL HUDSON	Title REG. ANALYST
Signature (Electronic Submission)	Date 08/08/2016
	LL OR STATE OFFICE USED TO DECOUD

Approved By Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. BUREAU OF LAND MANAGEMENT ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED CALLOR REVISED CALLOR REVISED OF FICE



August 4, 2016

AAO FED # 2
API # 30-015-32308
Eddy County, NM
Surface Casing: 8-5/8" 24# Set @ 327'
Production Casing: 5-1/2" 17# Set @ 4,143'

Objective: Isolate open perfs and TA wellbore

Producing Interval: 1,967-2,649'; 3,373-3,699'

Procedure:

1. POOH with rods and tbg

2. Set CIBP @ 1,900' and dump bail 35' of cmt

3. Fill casing with fluid and pressure test to 500 psi.

4. Record the test on a chart and submit for approval

Apache Corp. GROUP: Aug. 04, 2016 Permian North DATE: FIELD: Red Lake NE (BP) BY: HJG LEASE/UNIT: **AAO Federal** WELL: 2 Eddy COUNTY: STATE: New Mexico API: 30-015-32308 Spud Date: 8/20/02 KB = 3620'Rig Release Date: GL = 3611' Completion Date: 9/1/02 UL-C, Section-1, T-18S, R-27E 12-1/4" 8 5/8" 24# J-55 sct @ 327' w/ 250 sx 7-7/8" 5 1/2" 17# J-55 set @ 4143' w/ 925 sx - TOC at Surface DHC: 10/6/03 - Order CTB-531 DV Tool @ 2958' San Andres (7/2003) 1967-2649' (24 holes) Yeso (9/2002) 3373-36991 (20 shots) TD: 4150' PBD: 4127'

Conditions of Approval

Apache Corporation AAO - 02, API 3001532308 T18S-R27E, Sec 01, 430FNL & 2310FWL September 05, 2016

Operator is to have the BLM approved NOI procedure with applicable conditions of approval on location for this workover operation.

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well.

Temporary Abandonment (TA) BLM Status Approval Requires:

- 1. A Notice of Intent (NOI) Sundry (Form 3160-5) requesting approval to prepare the wellbore for a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A subsequent sundry report that describes compliance with:
 - a. All downhole production artificial lift equipment (tubing, rods, etc.) removed from the casing. A wellbore with a packer set just above producing or injection perforations with annulus integrity above the packer, and loaded with corrosion inhibiting fluid may be considered for TA status by passing a Mechanical Integrity Test.
 - b. The wellbore below all potential production is to be plugged back per permanent plugging procedures. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. A CIBP set above the top perforations to be permanently abandoned is to be capped with a minimum of 25 sacks cement and placed with tubing, or if the perforations are to be reopened 35 feet of cement may be bailed on the CIBP.
 - c. The wellbore filled with corrosion inhibited fluid.
 - d. At least 24 hours prior to conducting the Mechanical Integrity Test, contact the appropriate BLM office. Eddy County call Carlsbad 575-361-2822. Lea County call Hobbs 575-393-3612.
 - e. Documentation of a 500psig minimum BLM witnessed Mechanical Integrity Test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 35 to 75 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Verify all annular casing vents are plumbed to surface and those valves open to the surface during this pressure test. Pressure leakoff will be evaluated site specifically and affect approvals.
- 3. Submit a Subsequent Sundry Notice (Form 3160-5) requesting TA approval with a description of the preparation for temporary abandonment approval, a clear copy or the original Mechanical Integrity Test chart, a current wellbore diagram, and justification

- describing a substantial reason for the request, the expected wellbore use, and the estimated date the well will be returned to beneficial use.
- 4. This BLM TA NOI Approval is for WELLBORE PREPARATION ONLY. BLM IS NOT APPROVING TA Status FOR THIS WELL. If warranted, TA approval status for a specified time limit will be noted with BLM acceptance of the subsequent report of preparations and justification.
- 5. Workover approval is good for 90 days (completion to be within 90 days of approval).
- 6. Should Mechanical Integrity Test not prove wellbore integrity or not be conducted submit a procedure to repair or plug and abandon the well for BLM approval within 30 days of the MIT.