NM OIL CONSERVATION

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico **Energy Minerals and Natural Resources**

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

2RP-4006

huv 2 1 2016 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC. RECEIVED

			Rel	ease Notific	atio	n and Co	rrective A	ction	1					
NAB1	0328	OPERA	ГOR											
Name of Co		Contact Christine Alderman												
Address 60		Telephone No. 432-853-7059												
Facility Name Pintail 23 #8H						Facility Type production								
Surface Owner Mineral Owner						API No. 30-015-38657								
				LOCA	TIO	N OF RE	LEASE							
Unit Letter	Section	Township	Range	Feet from the		h/South Line	Feet from the	East/V	West Line County					
M	23	258	26E	250		s	800		W Eddy					
1	1 23	250	2013	· · · · · · · · · · · · · · · · · · ·	2 1002		L		T Date					
Latitude_32.10874_Longitude -104.26932 NATURE OF RELEASE														
Type of Release Produced water							Volume of Release 50 bbls Volume Reco					covered 2 bbls		
Source of Release piping							Date and Hour of Occurrence 11/20/2016			Date and Hour of Discovery 11/20/2016				
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Shelly Tucker/Heather Patterson/Mike Bratcher								
By Whom? Christine Alderman						Date and Hour								
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.								
☐ Yes ☒ No						NM OIL CONSERVATION								
If a Watercon	ırse was Im	pacted, Descr	ibe Fully.							ARTES	IA DI	STRICT		
	•									NOV	21	2016		
Describe Cause of Problem and Remedial Action Taken. A 2" threaded fitting corroded and failed.							RECEIVED							
Describe Area Affected and Cleanup Action Taken. The affected area was pasture area and was approximately 2' wide by 25' long. We will delineate and submit a work plan to remediate.														
regulations a public health should their or or the enviro	Il operators or the envi- operations had an	are required to ronment. The lave failed to a	o report at acceptant adequately OCD accep	e is true and comp nd/or file certain r ce of a C-141 repo investigate and r otance of a C-141	elease : ort by tl emedia	notifications a he NMOCD nate contaminat	nd perform correct arked as "Final R on that pose a the	ctive act Report" o reat to g	ions for rel loes not rel round wate	eases which ieve the ope r, surface wa	may o rator o ater, h	endanger of liability uman health		
1						OIL CONSERVATION DIVISION								
Signature: (Miotine alderman						1/ //								
Printed Name: Christine Alderman						Approved by Environmental Specialist:								
Title: ESH Supervisor						Approval Date: 112216 Expiration Date: NA								
E-mail Address: calderman@cimarex.com						Conditions of Approval:			Attached 🔽					
Date: 11/21/	2016	Phone: 43	2-853-705	i9				i S			-MAI			