

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NOV 29 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. <i>200737</i>		Contact: Amy Ruth	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329	
Facility Name: Golden Federal Battery #1		Facility Type: Exploration and Production	
Surface Owner: Federal		Mineral Owner: Federal	
		API No. 30-015-26931	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	8	21S	29E	1667	South	2300	West	Eddy

Latitude 32.491322° Longitude -104.007868°

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	32 bbls	Volume Recovered	30 bbls
Source of Release	3 Phase Vessel	Date and Hour of Occurrence	11/26/2016 time unknown	Date and Hour of Discovery	11/26/2016 approx. 10 am by operator
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required				
	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD) and Jim Amos/Shelly Tucker (BLM)				
By Whom?	Amy Ruth (within 2 hours of being notified)				
	Date and Hour 11/28/2016 11:19 am				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
	If YES, Volume Impacting the Watercourse. N/A				

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

Unused 3 phase vessel re-fitted and returned to operation. Fluids released from vessel through pressure relief valve and leaking Vic connections. Fluids escaped mostly into zero permeability containment.

Describe Area Affected and Cleanup Action Taken.*

The leak affected a total of about 3,168 square feet of caliche pad, zero permeability containment, and misted pasture east of the location. Free standing liquids were recovered via vacuum truck and equipment, tanks, and liner were power washed. Vessel was isolated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION	
Signature: 	Approved by Environmental Specialist: 
Printed Name: Amy C. Ruth	Approval Date: 11/29/16
Title: EHS Environmental Supervisor	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval:
Date: 11/29/2016 Phone: 432-661-0571	Attached <input checked="" type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-4017