

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
NOV. 24, 2016
RECEIVED
Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB11633633401

OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report		
Name of Company Devon Energy Production Company <i>10137</i>	Contact Jake Harrington, Production Foreman	
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 432-214-5175	
Facility Name Ross Ranch 10 Fed 1 SWD	Facility Type Salt Water Disposal	
Surface Owner Federal	Mineral Owner Federal	API No 30-015-29605

LOCATION OF RELEASE

Unit Letter H	Section 10	Township 26S	Range 31E	Feet from the 1980'	North/South Line North	Feet from the 660'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.0593872

Longitude: -103.7596054

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 15bbls	Volume Recovered 12bbls
Source of Release Transition fitting on water line	Date and Hour of Occurrence November 19, 2016 @ 12:00 PM	Date and Hour of Discovery November 19, 2016 @ 12:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, OCD	
By Whom? Mike McMahan, Asst. Production Foreman	Date and Hour Shelly Tucker, BLM November 19, 2016 @ 1:30 PM Mike Bratcher, OCD November 19, 2016 @ 1:26 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A transition fitting split on the water line due to internal corrosion. The valves on the line were shut to isolate the line and stop the release. Repairs have been completed.		
Describe Area Affected and Cleanup Action Taken.* Approximately 15bbls produced water was released onto the pad and into pasture. A vacuum truck was able to recover approximately 12bbls produced water. The release was located on the South side of the tanks on pad and into the pasture in approximately a 3'x100' area. An environmental agency will be contacted for remediation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Approved by Environmental Specialist: <i>Cynthia Wells</i>	
Title: Field Admin Support	Approval Date: <i>11/23/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: Sheila.fisher@dvn.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 11/22/16 Phone: 575.748.1829		

* Attach Additional Sheets If Necessary

2RP-4009