

NM OIL CONSERVATION

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

ARTESIA DISTRICT

DEC 06 2016

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

DEC 09 2016

RECEIVED

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
Compliance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1634429601

OPERATOR

X Initial Report

Final Report



Name of Company: Burnett Oil Co., Inc. 3080	Contact: Johnny Titsworth
Address: Burnett Plaza-Ste 1500, 801 Cherry St-Unit 9, Fort Worth, TX 76102	Telephone No. (432) 425-2891
Facility Name: Nosler Federal TB	Facility Type: Tank Battery
Surface Owner: BLM	Mineral Owner: BLM
API No. 30-015-38633	

LOCATION OF RELEASE

Unit Letter P	Section 12	Township 17S	Range 31E	Feet from the 799	North/South Line FSL	Feet from the 564	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.84420 Longitude: -103.81650

NATURE OF RELEASE

Type of Release: oil	Volume of Release: 3bbls	Volume Recovered: 0
Source of Release: Fire at Heater Treater	Date and Hour of Occurrence: 11:00 pm 12/5/16	Date and Hour of Discovery: 11:20 pm 12/5/16
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD - H. Patterson BLM - S. Tucker	
By Whom? Johnny Titsworth	Date and Hour: 12/6/16	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Fire at Heater Treater caused the release of oil. The majority of the oil was consumed by the fire, with small amounts left inside the lined facility as well as the location pad.		
Describe Area Affected and Cleanup Action Taken.* The impacted area is approx. 20'x50' inside the lined facility and a 40'x70' area on the pad. The area will be scrapped, with the impacted material being hauled to disposal.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Johnny Titsworth	Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 12/8/16	Expiration Date: N/A
E-mail Address: jtitsworth@burnettoil.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 12/6/16 Phone: (432) 425-2891		

* Attach Additional Sheets If Necessary

2RP-4028