District 1 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV State of New Mexico **Energy Minerals and Natural Resources** District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State

NM OIL CONSERVATION

ARTESIA DISTRICT

DEC 13 2016

Form C-141 Revised August 8, 2011

Final Report

RECEIVED to appropriate District Office in RECEIVED cordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action								
134	1951483	OPERATOR	Initial Report					
npany	COG Operating LLC 214/37	Contact:	Robert McNeill					
600 \	West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443					
ie:	MYOX 31 STATE COM #013H	Facility Type:	Tank Battery					

Surface Owner:

Name of Company:

Facility Name:

Address:

Mineral Owner:

API No. 30-015-37497

LOCA	ТЮ	DN	OF	REI	LEA	SE	

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	31	255	28E	660'	South	330'	East	Eddy

Latitude 32.0807419 Longitude 104.119072

NATURE OF RELEASE

Type of Release:	Volume of Release:	Volume Recovered:		
Oil	30bbls	28bbls		
Source of Release:	Date and Hour of Occurrence:	Date and Hour of Discovery:		
Valve	12-11-2016 11:15 am	<u>12-11-2016</u> 11:15 am		
Was Immediate Notice Given?	If YES, To Whom?			
🛛 Yes 🔲 No 🗂 Not Required	Mike Bratcher - NMOCD / Amber Groves - SLO			
By Whom? Robert Grubbs Jr.	Date and Hour: Mon	12/12/2016 10:55 AM		
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.			
Yes X No				
If a Watercourse was Impacted, Describe Fully.*				
Describe Cause of Problem and Remedial Action Taken.*				
esence eause of Froment and Achievan Frenon Funcil.				
The release was caused by a corroded valve on the water tank. Replaced	the valve with a new valve.			
Describe Area Affected and Cleanup Action Taken.*				
Describe rates rationed and Cheming reason raken,				
This release occurred within a lined facility. Vacuum trucks were dispate	ched to remove all freestanding fluids. Co	oncho will have the spill area evaluated		
for any possible contamination from the release and we will present a re-	mediation work plan to the NMOCD for a	approval prior to any significant		
remediation work.				
I hereby certify that the information given above is true and complete to	the best of my knowledge and understand	d that pursuant to NMOCD rules and		
regulations all operators are required to report and/or file certain release	notifications and perform corrective actions and perform corrective actions and perform corrective actions and the second	ons for releases which may endanger		
public health or the environment. The acceptance of a C-141 report by t should their operations have failed to adequately investigate and remedia	ne NMOCD marked as Final Report do	bes not reneve the operator of nating		
or the environment. In addition, NMOCD acceptance of a C-141 report	does not relieve the operator of responsib	bility for compliance with any other		
federal, state, or local laws and/or regulations.	abes not reneve are operator of response			
······································	OIL CONSERV	ATION DIVISION		
Signature: Zalut day		TT x		
	Signed By			
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist:			
	12 12 11	NIA		
Title: Senior HSE Coordinator	Approval Date: 12 3 10 E	Expiration Date: N/A		
E-mail Address: rgrubbs@concho.com	Conditions of Approval:			
	Concerns or replicing	Attached 🕅		
Date: December 13, 2016 Phone: 432-683-7443		1 / 1		
Attach Additional Sheets If Necessary	1	700 102		
		4KY-400		