

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1230 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

DEC 21 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED Only to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action



| | | | | | |
|--|--|------------------------------|--|--|--|
| <i>NAB1636346190</i> | | OPERATOR | | <input checked="" type="checkbox"/> Initial Report | <input checked="" type="checkbox"/> Final Report |
| Name of Company Oxy Permian Ltd. <i>116696</i> | | Contact Casey Summers | | | |
| Address PO Box 4294; Houston, TX 77210 | | Telephone No. (575) 513-8289 | | | |
| Facility Name Cedar Canyon 16 SWD #003 | | Facility Type SWD Facility | | | |
| Surface Owner Draper/McDonald | | Mineral Owner | | API No. 30-015-41324 | |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|-----------------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| D | 16 | 24S | 29E | | | | | Eddy County, NM |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | |
|--|---|----------------------------|
| Type of Release Oil and Produced water | Volume of Release 2 bbls oil, 4 bbls produced water | Volume Recovered 6 bbls |
| Source of Release Tank spill due to frozen valve | Date and Hour of Occurrence 12/18/16 | Date and Hour of Discovery |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Mike Bratcher, Crystal Weaver- NMOCD | |
| By Whom? Kathy Purvis, BBC International | Date and Hour 12/20/16 @ 9:42 am | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* A frozen valve caused a skim tank to spill over into the lined containment. A vacuum truck recovered all the fluids. | | |
| Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 40' x 40' on location inside the lined containment. Remediation was completed by recovering all the leaked fluids inside the lined containment. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Casey Summers | Approved by Environmental Specialist:  | |
| Title: NM Environmental Advisor | Approval Date: 12/28/16 | Expiration Date: N/A |
| E-mail Address: Casey.Summers@oxy.com | Conditions of Approval: | |
| Date: 12-21-16 Phone: (575) 513-8289 | FINAL | |
| | Attached <input type="checkbox"/> | |

* Attach Additional Sheets If Necessary

2RP-4050