## **NM OIL CONSERVATION**

ARTESIA DISTRICT

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

State of New Mexico Energy Minerals and Natural Resources 2 7 2016

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC. RECEIVED

1220 S. St. Fran	cis Dr., Sant	a Fe, NM 8750:	5	S	anta F	e, NM 875	05			
			Rele	ease Notifi	catio	n and Co	rrective A	ction		
						OPERA'	ГOR	☐ Initi	al Report     Final Repor	
						Contact EL GONZALES				
Address 2130 W BENDER HOBBS NM 88240						Telephone No. 575-738-1739 EXT. 1505				
Facility Nar	ne JLKE	EEL B 22				Facility Typ	e INJECTION	WELL E-FILE	E # 2277	
Surface Owner BLM Mineral Owner						BLM		API No. 30-015-05082 LEASE NO NML CO29435B		
					. ===				110 11111111111111111111111111111111111	
Unit Letter   Section   Township   Range   Feet from the   North/South Line   Feet from the   East/West Line   County										
Unit Letter Section Township Range 31E Feet from the North					Norti	/South Line   Feet from the   East/West I		East/West Line	County   EDDY	
		Lati	tude32	.5141_ Longit	ude1	03.5353 (RE	LEASE SITE)_	**************************************		
				NAT	<b>TURE</b>	OF REL	EASE			
Type of Release PRODUCED WATER / OIL							Volume of Release 40 / 7 Volume Recovered 23 / 2			
Source of Release BETWEEN WELL HEAD AND BOP						Date and Hour of Occurrence Date and Hour of Discovery 01/06/2012 9AM 01/06/2012 9:30 AM				
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? TERRY GREGSTON BLM MIKE BRATCHER NM OCD				
By Whom? JOE HERNADEZ						Date and Hour 01/06/2012 2:30 PM				
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.  N/A				
If a Watercou	ırse was Im	pacted, Descr	ibe Fully.	*						
						•				
N/A										
Describe Cau	ise of Probl	em and Reme	dial Action	n Taken.*						
BCM Plugging	crew drilled	l out plug on we	ell and relea	sed pressure from o	down hol	e. Flange on	lina fluid waa ralaas	dd		
BOP stripped a	ing released	nuius. Vaccum	truck and to	wo pits on location	Tillea Wi	in muid, after m	ling fluid was releas	sed on ground.		
Describe Are	a Affected	and Cleanup	Action Tak	ren * Fluid was rel	leased on	sloan and flow	ed down hill for ann	roximately 1650 ft. f	ollowing an arroyo	
The spill was a			iction rus	ton. I luiu was to	cused on	Sloup wid now	va do viii iiii ioi app	TOAMHALOTY TOO IL. I	onowing air arroyo.	
Delineation of	omplete									
	•									
I hereby certi	fy that the	information g	iven above	is true and comp	plete to	the best of my	knowledge and u	nderstand that pur	suant to NMOCD rules and	
regulations a	ll operators	are required t	o report ar	nd/or file certain	release	notifications a	nd perform correc	tive actions for rel	eases which may endanger	
									ieve the operator of liability r, surface water, human health	
									ompliance with any other	
		ws and/or regi			· · · · · · · · · · · · · · · · · · ·					
		$\overline{}$	1	/			OIL CON	<u>SERVATION</u>	DIVISION	
Signature: The same of the sam							1///			
- //							Approved by Environmental Specialist:			
Printed Name: E. L. Goppares										
Title: Produc	tion Superv	risor Producti	on Superv	isor		Approval Date: 12/21/16 Expiration Date:				
E-mail Addre	ess: ELgonz	rales@linnene	rgy.com			Conditions of	Approval:	0	Attached	
Date: 9-	7-16			Phone:505-504-8	8002		th	N		

UP-2277