

**NM OIL CONSERVATION**ARTESIA DISTRICT State of New Mexico  
Minerals and Natural ResourcesForm C-141  
Revised August 8, 2011District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505Oil Conservation Division  
RECEIVED 20 South St. Francis Dr.  
Santa Fe, NM 87505Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.**Release Notification and Corrective Action**

2RP-712

**OPERATOR**☐ Initial Report ☒ Final Report

Name of Company LINN Energy	Contact EL GONZALES	
Address 2130 W BENDER HOBBS NM 88240	Telephone No. 575-738-1739 EXT. 1505	
Facility Name J L KEEL B 22 E-FILE # 712	Facility Type INJECTION WELL	
Surface Owner BLM	Mineral Owner BLM	API No. 30-015-05082 LEASE NO NML CO29435B

**LOCATION OF RELEASE**

Unit Letter L	Section 5	Township 17S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County EDDY
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.8620 Longitude 103.8983 (RELEASE SITE)

**NATURE OF RELEASE**

Type of Release PRODUCED WATER / HYDROCARBONS	Volume of Release UNKNOWN	Volume Recovered UNKNOWN
Source of Release INJECTION WELL LOCATION, BUT COULD POSSIBLY BE AN UNAUTHORIZED DUMPING	Date and Hour of Occurrence UNKNOWN	Date and Hour of Discovery 8 NOV 10 (BLM)
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*

N/A



Describe Cause of Problem and Remedial Action Taken.\*

This is an active injection well site with the release site on the north side of the location. It appears that the release is from a truck or tank. The release fluids ran down the hillside to the west and crossed the lease road. The affected area will be delineated and a work plan submitted to NM OCD and BLM for review and approval.

Describe Area Affected and Cleanup Action Taken.\*

Delineation complete

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: E. L. Gonzales	Approved by Environmental Specialist: 	
Title: Production Supervisor Production Supervisor	Approval Date: 12/21/16	Expiration Date:
E-mail Address: ELgonzales@linnenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9-7-16	Phone: 505-504-8002	

Site inspection confirmed  
work was completed see also 2RP-2277