

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

DEC 23 2016

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

0AB1701231371

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company EOG Y Resources, Inc.	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>th</sup> Street	Telephone No. 575-748-1471	
Facility Name Patsy BPI State #7	Facility Type Battery	

Surface Owner State	Mineral Owner State	API No. 30-005-29121
------------------------	------------------------	-------------------------

## LOCATION OF RELEASE

Unit Letter O	Section 35	Township 11S	Range 31E	Feet from the 660	North/South Line South	Feet from the 1980	East/West Line East	County Chaves
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 33.31555 Longitude 103.79004

## NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30 B/PW	Volume Recovered 30 B/PW
Source of Release Fiberglass Tank	Date and Hour of Occurrence 12/9/2016; AM	Date and Hour of Discovery 12/9/2016; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kristen Lynch/NMOCD I	
By Whom? Robert Asher/EOG Y Resources, Inc.	Date and Hour 12/9/2016; PM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Ball valve on the 210 bbl fiberglass tank froze and broke. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 30' X 40' within the lined and bermed battery. Vacuum truck recovered all the produced water, with the liner in very good condition. The valve was repaired and the well put back into service. Depth to Ground Water: >100' (approximately 100', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on the battery being lined/bermed, EOG Y Resources, Inc. requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Signed By  Approved by Environmental Specialist:	
Title: Sr. Environmental Supervisor	Approval Date: <u>1/10/17</u>	Expiration Date: <u>N/A</u>
E-mail Address: Robert.Asher@eogresources.com	Conditions of Approval: <u>FINAL</u>	Attached <input type="checkbox"/>
Date: December 23, 2016	Phone: 575-748-4217	

\* Attach Additional Sheets If Necessary

2RP-4067