

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-05-20341

Release Notification and Corrective Action

NMLB0525950563

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Devon Energy Production Co. LP	Contact: Jennifer Van Curen
Address: PO Box 250; Artesia, NM 88211	Telephone No.: 505-748-0160
Facility Name: Todd 36 State 1	Facility Type: Battery

Surface Owner	Mineral Owner	Lease No. K-952
---------------	---------------	-----------------

LOCATION OF RELEASE

Unit Letter K	Section 36	Township 23S	Range 31E	Feet from the 1980	North/South Line NORTH	Feet from the 1980	East/West Line WEST	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release: water	Volume of Release: 2000	Volume Recovered: 1800
Source of Release: Valve on disposal well had a hole in valve body	Date and Hour of Occurrence 8:00 pm 8-19-05	Date and Hour of Discovery 8:00 pm 8-19-05
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Joe Hawkes at NMOCD	
By Whom? Joe Huber	Date and Hour: 8-19-05 at 9:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

RECEIVED

FEB 13 2006

OCU-AMT 1091A

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Hole in valve appears to a manufacturing defect. Built berm to control the spill. Called vacuum trucks to pick up standing water. Changed out valve on wellhead using a valve from a different manufacturer and style.

Describe Area Affected and Cleanup Action Taken.\*

Spill stayed on location. Hauled contaminated caliche pad material to CRI (disposal). Replaced contaminated caliche with fresh.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Jennifer Van Curen</i>	Approved by District Supervisor: <b>TIM GUM</b> by MB <i>[Signature]</i>	
Printed Name: Jennifer Van Curen	Approval Date: 3/22/06	Expiration Date:
Title: Production Field Tech	Conditions of Approval:	Attached <input type="checkbox"/>
E-mail Address: Jennifer.vancuren@dvn.com		
Date: 2/13/06	Phone: 748-0160	

\* Attach Additional Sheets If Necessary