

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Tony Delfin
Acting Cabinet Secretary

David R. Catanach, Division Director
Oil Conservation Division



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

16-Mar-17

TANDEM ENERGY CORPORATION

2700 Post Oak Blvd Suite 1000
Houston TX 77056-7056

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

BEDINGFIELD FEDERAL No.001				J-1-17S-29E	30-015-02835-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/16/2017	Routine/Periodic Violations Surface Leaks/Spills	Tony Morales	Yes	No	6/19/2017	iTM1707536865
Comments on Inspection:		OK. All Equipment and Location in Good Shape. PJO STAINING AROUND WELL HEAD				

SQUARE LAKE 12 UNIT No.101				O-1-17S-29E	30-015-02838-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/16/2017	Routine/Periodic Violations General Housekeeping (Rule 114)	Tony Morales	Yes	No	6/19/2017	iTM1707537254
Comments on Inspection:		OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELLHEAD. TANK BATTERIES NO SECONDARY IMPERMEABLE CONTAINMENT/BERM NO WINDSOCK /PLACARDS. OLD TANK ON TANK BATTERY LOCATION.				

SQUARE LAKE 12 UNIT No.118

O-12-17S-29E

30-015-02954-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/16/2017	Routine/Periodic	Tony Morales	Yes	No	6/19/2017	iTM1707533094
Violations Absent Well Identification Signs (Rule 103) Surface Leaks/Spills General Housekeeping (Rule 114)						
Comments on Inspection: All Equipment and Location in Good Shape. PJO. STAINING AROUND WELL HEAD / LOCATION. STAINED AREA APPROX 15' X 120' LOCATION SIGN NOT VISIBLE CONTAMINATED MATERIAL ON FLOWLINE CUTOFFS AWAY FROM PJ STAINING DOWN ROAD WAY.						

SQUARE LAKE 12 UNIT No.107

E-12-17S-29E

30-015-02969-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/16/2017	Routine/Periodic	Tony Morales	Yes	No	6/19/2017	iTM1707536012
Violations General Housekeeping (Rule 114)						
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELLHEAD						

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,


Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.