Form 3150-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

**SUNDRY NOTICES AND REPORTS ON WELLS** 

NMOCD Artesia FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

## 5. Lease Serial No.

NMNM40659

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agree	ement, Name and/or No.	
Type of Well		8. Well Name and No. PURE GOLD D FI	EDERAL 4				
Name of Operator     OXY USA INC.		9. API Well No. 30-015-27131					
3a. Address P.O. BOX 50250 MIDLAND, TX 79710  3b. Phone No. Ph: 432-66 Fx: 432-68					10. Field and Pool or Exploratory Area SAND DUNES DELAWARE, W		
4. Location of Well (Footage, Sec., T.		11. County or Parish, State					
Sec 28 T23S R31E SWSW 33 32.269066 N Lat, 103.790222		EDDY COUNTY	′, NM				
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION			ACTION				
☐ Notice of Intent	☐ Acidize	☐ Dee	□ Deepen		on (Start/Resume)	■ Water Shut-Off	
	☐ Alter Casing	□ Нус	raulic Fracturing	☐ Reclama	ation	■ Well Integrity	
Subsequent Report	□ Casing Repair	☐ Nev	■ New Construction		lete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans		g and Abandon		arily Abandon	•	
13. Describe Proposed or Completed Ope	☐ Convert to Injection	☐ Plu		☐ Water D	-		
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Attached that the site is ready for from TD-8130' PBTD-5909' Performance of the performance of	rk will be performed or provide operations. If the operation resonandonment Notices must be fillinal inspection.  Se 6290-7914' CIBP 6251  Group to the graph of	the Bond No. o sults in a multip ed only after all temporarily a pot pattern, on the succe would include advance.	n file with BLM/BIA le completion or recorrequirements, including the status. On the Pure Goldess of the response this well.	Required sub impletion in a n ing reclamation OXY is curred d D Federal se, OXY will cepted	ently #4  ART	ONSERVALION ESIA DISTRICT PR 1 0 2017	
Name(Printed/Typed) DAVID ST	Electronic Submission #: For OX Committed to AFMSS for p	Y USA INC	sent to the Carlsb DEBORAH MCKI	ad	14/2017 ()		
Signature (Electronic Submission)			Date 02/09/20	O17 ACC	EPTED FOR I	PCORD	
	THIS SPACE FO	R FEDERA	AL OR STATE (	OFFICE US	SE /		
Approved By  Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the second of the sec	uitable title to those rights in the act operations thereon.  U.S.C. Section 1212, make it a	subject lease crime for any p	Title Office erson knowingly and ithin its jurisdiction.	BUR willfully to ma	MAR 2.8 30  OF LAND MANA ARI SPAD FIELD OF the to any department or	deme de la companya d	
Emilio maj mise, nettrons or mandment	- Tepresentations do	Indicot w	- Januaronon.	<del>//</del>	<del></del>	<del></del>	

### Additional data for EC transaction #366570 that would not fit on the form

32. Additional remarks, continued

Witnessed by BLM-Chase Messer.

# Inspection Remarks

tdentifier WK	Case Number NMNM40659 Insp Type WK
Date 01/17/2017	Type 312011 Open Date 01/13/2016
Author CHASE MESSER	Case Name PURE GOLD D FED Close Date
Subject <b>INSP</b>	
('alceory GENERAL	
API / Fac II) 3001527131	OXY US
Well / Fac Name PURE GOLD D FED	OXY USA INCORPORATED
Number 4	

SP production equipment was in good order and had been prepped for TA


Category

Date

GENERAL 01/17/2017

HS production hands and personnel were properly dressed and had all PPE, appropriate measures such as whip checks were installed and in good order.

CS. Arrived on site met with Production tech Michael chambers from OXY, verified dates and SN on chart recorder and also verified it was zeroed out. Pressured up to 500PSI on casing and it held with 0 loss in pressure for 30 mins.



### Well and Notice Remarks

Doc Number 96A/R5345A	Doc Typ		Case IID IM40659	Туре 312011	Name PURE GOLD DIFED
AP1 300152713100S1	PURE GOL	Well Name D D FED	4	Number OX	Operator (Y USA INCORPORATED
Duc Number 17JASQ113SE 16JLR3116SE 16JLR31	Date 12/13/2016 64/56/2016 12/09/2015 68/21/2014 68/21/2014 68/23/2008 03/01/2008	JENNHEER SAM PRISCULLATE JAMES LICHT DENAM NEGRE DENAM NEGRE HOURT SAMADI GENE HUNT GENE HUNT GENE HUNT ARRS APPROVAIL GENE HUNT ARRS SAPROVAIL GENE HUNT ARRS SAPROVAIL GENE HUNT ARRS SAPROVAIL GENE HUNT ARRS SAPROVAIL GENE HUNT ARRS SAPROVAIL GENE HUNT ARRS APPOCAN ARRS APPOCAN ARRS APPOCAN ARRS APPOCAN ARRS APPOCAN ARRS APPOCAN ARRS APPOCAN ARRS APPOCAN ARRS APPOCAN	REZ SES SES SES SES SES SES SES SES SES S	SUC SUC INSI INSI INSI INSI INSI OTI- INSI INSI INSI INSI INSI INSI INSI IN	GENERAL GENERAL CESS APPROVAL CESS APPROVAL CESS APPROVAL CESS APPROVAL P INSP

TD-8130 PBTD-5907 Peds-6780 T814 COP-0751

OXY USA fine respectfully requests an extension to the temporarity abandon status. OXY is currently working towards implementing a pilot water flood inten goot pattern, and the Pure Gold D Federal 24 is located just cutside of the proposed pilot. Depending on the success of the response, OXY will likely expand the flood throughout the entire field which would include this well.

- 1 Notify BLWNMOCD of casing interity test 24hrs in advance
- 2 RU pump truck, circulate well with treated water, pressure test casing to 500# for 30min
- Approved 12/14/2016 JAM This well has not porduced since 09/2014. Last extension: 6 months only. Plug or produce by 08/12/2017. Following COAs apply.
- Approved for a period of 6 months ending 08:12/2017 subject to conditions of approval Temporary Abandonment of Wells on Federal Lands Conditions of Approva!
- A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162 3 4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.
- Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:
  - 1 A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT)
    - 2.A description of the temporary abandonment procedure
- a A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cament plug is used, the top of the cement must be verified by tagging. CIBP must be capped with miximum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
  - b. The weitbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
  - c. All downhole production/aspection equapment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer
- d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- a. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County 575-361-2822; Lea County 575-393-3612
- 3 Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned "43 CFR 3162-34 (4) The operator shalf promptly plug and abandonwells in which oil or gas is not encountered in paying quantities
  - Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator
- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with all perforations and CiBP's and tops of cement on CiBP's
  - 2 Describes the temporary abandonment procedure
  - 3 Attaches a clear copy or the original of the pressure test chart
  - 4 Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.
  - If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:
    - A procedure to repair the casing so that a TA approval can be granted
       2.A procedure to plug and abandon the well.
  - Pure Gold D Fed 4

    1 Well is approved to be TA/SI for a period of 12 months or until 38/12/2017

    2.This will be the last 1A approval for this well.

    3 Must submit NO! to recomplete or NO! to PAA. Must be submitted by 08/12/2017

    4 COA's met at this time.