

Received 7/18/2016

NMOCD Dist 2

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-141

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1715035797

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company <i>10/37</i>	Contact Danny Velo, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575.703.3360
Facility Name Coral PWU 28 4H	Facility Type Oil Well

Surface Owner State	Mineral Owner State	API No 30-015-39328
---------------------	---------------------	---------------------

LOCATION OF RELEASE

Unit Letter P	Section 28	Township 19S	Range 29E	Feet from the 330	North/South Line FSL	Feet from the 990	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.625395

Longitude: -104.074521

NATURE OF RELEASE

Type of Release Produced Water (PW)	Volume of Release 20BBLS	Volume Recovered 0BBLS
Source of Release Hole in the fire tubing on heater treater	Date and Hour of Occurrence 7/14/2016 @ 10:00AM	Date and Hour of Discovery 7/14/2016 @ 10:00AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher	
By Whom? Jesse Armendariz, Assistant Production Foreman	Date and Hour OCD-Mike Bratcher-7/14/2016 @ 11:30AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

20 BBLS of PW was released due to hole in the fire tubing on heater treater from normal wear and tear resulting in a fire on location. Loco Hills Fire Department was contacted and extinguished the fire. All tubing and casing on the Coral 28- 1, 2, 3, 4, 5, 6, and 7 were shut in and the inlet and outlet valves on the vessels from the production heater were also shut in to prevent further release. All battery power was shut off at disconnect and Supervisory Control and Data Acquisition Tech (SCADA) disconnected battery power to SCADA Panel. Repairs will be made.

Describe Area Affected and Cleanup Action Taken.*

20BBLS PW released from a hole in the fire tubing on the heater treater. 0BBLS PW were recovered. The North East Side of location was where the fire occurred originating from the heater treater and the approximate total affected area is 113ft by 90ft all contained on pad. An environmental company will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dana DeLaRosa</i>	OIL CONSERVATION DIVISION Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Printed Name: Dana DeLaRosa		
Title: Field Admin Support	Approval Date: <i>5/26/17</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>dana.delarosa@dvn.com</i>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO <i>10/26/17</i>	
Date: 7/18/2016 Phone: 575.746.5594		

* Attach Additional Sheets If Necessary

Note: Late entry by OCD

2RP-4229