State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary **David Catanach** Division Director



Response Required - Deadline Enclosed

26-May-17

MCCAW ENTERPRISE LLC 202 CROSSBOW ROAD ARTESIA NM 88210-

Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 19.15.25.8 (3) WELLS TO BE PROPERLY ABANDONED of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that the well is no longer usable (e.g., a dry hole), or one year after last production.

To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the. well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are

1. Immediately restore the well(s) to production, injection or disposal as applicable. Submit Form C-103 stating how and when wells became active and monthly file electronically Form C-115

- 2. Request 'Temporary Abandoned' status pursuant to Rule 19.15.25.13 on Form C-103, which requires that you set a plug. and conduct a mechanical integrity test
- 3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 19.15.25.9 on Form C-103 and, proceed with
- . plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved

In the event that a "**PLAN OF ACTION** "is not received within thirty days of this letter and all compliance issues completed by. the "Corrective Action Due By" date shown above, further enforcement will occur

IDLE WELL INSPECTION DETAIL SECTION					
MCCAW BT 001	G-14-17S-25E	30-015-20384-00-00	Inspection No. iTWG1714541788		
Inspection Date: 5/	25/2017 11:36:24 AM	Corrective Action Due by: 8/28/2017			
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?		
Routine/Periodic	Tim Gum	Yes	No		
Comments on Inspection	on: Idle Well.PJ.PO.ALL VAL POLPULATED AREA. PICTURES TAKEN.	VES OPEN,FLOWLINE CO	NNECTED. BTTY3 TKS,1 GB, 1 SP		
MCCAW BT 002	H-14-17S-25E	30-015-20447-00-00	Inspection No. iTWG1714540376		

Inspection Date: 5/25/2	17 11:12:54 AM Corrective Action Due by: 8/28/2017		ive Action Due by: 8/28/2017
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic Comments on Inspection:	CONNECTED.	Yes SG VALVES OPENED , FLO	No WLINE VALVECLOSED &
	POPULATED AREA. PICTURES TAKEN .		
MCCAW BT 003	A-14-17S-25E	30-015-21820-00-00	Inspection No. iTWG1714535947
Inspection Date: 5/25/	017 9:58:58 AM Corrective Action Due by: 8/28/2017		
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic Comments on Inspection: MCCAW BT 004 Inspection Date: 5/25/	CONNECTED. MOTOR A POWER OFF.	AND BELTS NOT CONNECTE NG : FLOW / RE-INSTALLING 30-015-21867-00-00	No LOWLINE VALVE OPEN AND D. ELECTRIC METER REMOVED AN G MOTOR,BELTS AND POWER. Inspection No. iTWG1714537610 ive Action Due by: 8/28/2017
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic Comments on Inspection:	Tim Gum	Yes	No CONNECTED. CAPABALE OF
MCCAW BT 006	H-14-17S-25E	30-015-24213-00-00	Inspection No. iTWG1714539356
Inspection Date: 5/25/	2017 10:55:53 AM	17 10:55:53 AM Corrective Action Due by: 8/28/2017	
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tim Gum	Yes	No
Comments on Inspection:	idle Well.PJ.PO. TBG & C POPULTED AREA. PICTURES TAKEN.	SG VALVES OPEN, FLOWLI	NE VALVE OPENED. & CONNECTED

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely,

Im le. Sum

Artesia OCD District Office

* Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas.