Submit 1 Copy To Appropriate District Office	State of New Mexico			Form C-103	
District I - (575) 393-6161	Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION		Trmt Labras	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210			30-015-20501		
District III – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE	FEE 🛛	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sama 1 C, INF	vi 87505	6. State Oil & Gas	Lease No.	
	TICES AND REPORTS ON WE	ELLS	7. Lease Name or U	Jnit Agreement Name	
(DO NOT USE THIS FORM FOR PROP			Santa Fe Land SWI		
DIFFERENT RESERVOIR. USE "APPL	ICATION FOR PERMIT" (FORM C-10	01) FOR SUCH	8. Well Number	54000	
PROPOSALS.)	Gas Well Other SW	T	1		
1. Type of Well: Oil Well					
2. Name of Operator EOG Y Resources, Inc.			9. OGRID Number 025575		
3. Address of Operator				10. Pool name or Wildcat	
104 South Fourth Street, Artesia, NM 88210			SWD; Canyon		
			5 W D, Curryon	96184	
4. Well Location Unit Letter i :	1980 feet from the	South line and	660 feet from the	ne <u>East</u> line	
Section 17	Township 19S	Range 26E	NMPM Eddy	County	
	11. Elevation (Show whether				
	· ·	395'GR			
12. Check	Appropriate Box to Indicate	te Nature of Notice	e, Report or Other D	ata	
NOTICE OF II	NTENTION TO:	9111	BSEQUENT REP	OPT OF:	
PERFORM REMEDIAL WORK		REMEDIAL WO		LTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A				<u></u> -	
PULL OR ALTER CASING		CASING/CEME		AND A	
	<del></del> -	CASING/CEIVIE	M 1000		
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM					
OTHER:	, –	OTHER: MIT		M	
	pleted operations. (Clearly state		nd give pertinent dates.	including estimated date	
	ork). SEE RULE 19.15.7.14 N				
proposed completion or re					
5/25/17 – MIRU. Pumped 45 bbls					
POOH with tubing, pin ends on tubing were ate up on most of the pipe. Found hole in jt 238, top connection had a hole and bottom sub					
on packer was ate up due to corrosion.					
5/30/17 – RIH 5-1/2" AS-1 nickel plated packer with on/off tool with 2.25" F profile and 2-7/8" L-80 IPC tubing to 7711'. Circulated					
160 bbls packer fluid down annulus. ND BOP. Loaded casing with 2 bbls. Pressure tested to 550 psi for 30 min, held good.					
5/31/17 – Pressure tested casing to 540 psi for 30 minutes. MIT successful. Bled down pressure to 0 psi.					
Original MIT was obtained by NM	OCD-Artesia.				
ong	002 11111111				
			NM	OIL CONSERVATION	
				ARTESIA DISTRICT	
				JUN <b>1 6</b> 2017	
Spud Date:	Rig Releas	se Date:		RECEIVED	
		L			
I hereby certify that the information	above is true and complete to t	he best of my knowled	ge and belief.		
SIGNATURE ((\)\(\)\(\)\(\)	TITLE	Regulatory Specia	ılist DATE June	14 2017	
SIGNATURE	11122	regulatory opeoic	inst DixIL	11,2017	
Type or print name Tina Hu	<u>ierta</u> E-mail address:	tina_huerta@eogres	ources.com PHONE:	575-748-4168	
For State Use Only	,				
1 DDD 01 DD 1	10505	2. Michael	AGGIED	alpalia	
APPROVED BY: LULYAN Conditions of Approval (if any):	NGE TITLE	OMPLIANCE (	DATE DATE	6/20/14	