## IM OIL CONSERVATION

•

.

ANTECIA DISTRICT			
Submit One Copy To Appropriate District Office ULIN 1 C 2017 State of N	New Mexico	Form C-103	
Office JUN <b>16</b> Energy, Minerals a	and Natural Resources	January 20, 2011	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-015-21603	
District II 1301 W. Grand Ave., Artesia, NM 8821 RECEIVED CONSERV.	ATION DIVISION	5. Indicate Type of Lease	
District III 1220 South	St. Francis Dr.	STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe,	, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM			
87505 SUNDRY NOTICES AND REPORTS ON	WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		NG Phillips State	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number 15	
2. Name of Operator		9. OGRID Number	
COG Operating LLC		229137	
3. Address of Operator		10. Pool name or Wildcat	
One Concho Center, 600 W Illinois Ave, Midland, TX 79701	l	East Empire; Yates-7 Rivers	
4. Well Location			
Unit Letter J: 2310 feet from the South line and 2	2310 feet from the East line		
Section 27 Township 17S Range 28E NMPM	A County <u>Eddy</u>		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3655			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
PERFORM REMEDIAL WORK DUILD PLUG AND ABANDON			
$\equiv$			
OTHER:	□ ⊠ Location is r	eady for OCD inspection after P&A	
All pits have been remediated in compliance with OCD ru			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
<u>I DRMANUMIER STAME DON'THE MARKER STORE ACE.</u>			
$\boxtimes$ The location has been leveled as nearly as possible to orig	inal ground contour and has	been cleared of all junk, trash, flow lines and	
other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.	re plan. An now mes, prod	luction equipment and junk have been removed	
$\boxtimes$ All metal bolts and other materials have been removed. Po	ortable bases have been remo	oved. (Poured onsite concrete bases do not have	
to be removed.)			
All other environmental concerns have been addressed as			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines.			
If this is a one-well lease or last remaining well on lease, all electrical service, poles and lines, not to include primary service			
company equipment, has been removed from lease and well loo		adula an inspection	
When all work has been completed, return this form to the appr	opriate District office to sch	ledule all inspection.	
SIGNATURE T	TITLE Lead Regulatory An	nalyst DATE <u>2/10/17</u>	
- ···			
TYPE OR PRINT NAME <u>Kanicia Castillo</u> E-MAIL:	kcastillo@concho.com	PHONE: <u>432-685-4332</u>	
For State Use Only			
112111	A ALTINA	are in a second lat la mit	
APPROVED BY: flatt f but	TILE COMPLIANCE	OFFICER DATE 6/26/2017	
Conditions of Approval (if any):			