State of New Mexico Energy, Minerals and Natural Resources Department


Susana Martinez

Governor

Ken McQueen Cabinet Secretary

Matthias Saver

Deputy Cabinet Secretary





Response Required - Deadline Enclosed

Field Inspection Program "Preserving the Integrity of Our Environment"

03-Jul-17

HUDSON OIL COMPANY OF TEXAS

616 TEXAS STREET FORT WORTH TX 76102

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION M-24-17S-31E 30-015-05373-00-00 **PUCKETT B No.001** *Significant Corrective Inspection Type Inspection Violation? Inspection No. Inspector Non-Compliance? Action Due By: Date 07/03/2017 Routine/Periodic **Tony Morales** Yes No 10/6/2017 iTM1718442422 Violations Idle well (Rule 201) **Comments on Inspection:** OK. All Equipment and Location in Good Shape. NO PJ LOCATION SIGN NOT VISIBLE. 19.15.16.8 PUCKETT B No.008 C-25-17S-31E 30-015-05398-00-00 Corrective *Significant Inspection Inspection No. Violation? **Type Inspection** Inspector Date Non-Compliance? Action Due By: 07/03/2017 Routine/Periodic **Tony Morales** Yes No 10/6/2017 iTM1718443355 **Violations** Absent Well Identification Signs (Rule 103) OK. All Equipment and Location in Good Shape. NO PJ LOCATION SIGN NOT VISIBLE. **Comments on Inspection:** 19.15.16.8

PUCKETT B No.018 L-25-17S-31E 30-015-05408-00-00

Type Inspection Date

Inspection

Violation? Inspector

*Significant Non-Compliance?

Corrective Action Due By:

Inspection No.

07/03/2017 Routine/Periodic Tony Morales

Yes

No

10/6/2017

iTM1718444838

Violations

Absent Well Identification Signs (Rule 103)

Comments on Inspection:

OK. All Equipment and Location in Good Shape.

LOCATION SIGN NOT VISIBLE 19.15.16.8

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely.

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.