

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 30 2017

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1718735670

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company Cimarex Energy		Contact Christine Alderman	
Address 600 N Marienfeld Ste 600 Midland TX		Telephone No. 432-853-7059	
Facility Name Liberty 24 SWD Federal com #1		Facility Type SWD	
Surface Owner Fed		Mineral Owner	
		API No. 30-015-33094	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	24	25S	26E	1650	N	1200	W	Eddy

Latitude 32.1181259 Longitude -104.2509842

NATURE OF RELEASE

Type of Release produced water	Volume of Release 117 bbls	Volume Recovered 117 bbls
Source of Release fiberglass tank	Date and Hour of Occurrence 6/27/2017	Date and Hour of Discovery 6/28/2017
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Shelly Tucker	
By Whom? Christine Alderman	Date and Hour 6/30/2017	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

During heavy storms, the fiberglass slop oil tank separated from the base and landed approximately 30' away. There was no fire, and all released fluids stayed within the lined berm.

Describe Area Affected and Cleanup Action Taken.*

The inside of the berm was intact and all fluids were recovered with a vacuum truck.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Christine Alderman</i>	Approved by Environmental Specialist: <i>Crystal Wu</i>	
Printed Name: Christine Alderman	Approval Date: 7/3/17	Expiration Date: N/A
Title: ESH Supervisor	Conditions of Approval: Final - This was	
E-mail Address: calderman@cimarex.com	Attached <input type="checkbox"/>	
Date: 6/30/2017 Phone: 432-853-7059		

* Attach Additional Sheets If Necessary

Please refer to the New Mexico Oil Conservation Division Website for updated form(s) at:
<http://www.emnrd.state.nm.us/OCD/forms.html>
Thank you

attached to an email that has a statement that the "liner is intact and all fluids were recovered." (email was scanned and is included behind this form)