Artesia

Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OMB No. 1004-0137

E	exputes: January 3	1,2018
b. Lease Serial No.	NM 12557	
. If Indian, Allottee	e or Tribe Name	

FORM APPROVED

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

N/A abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2 N/A 1. Type of Well 8. Well Name and No. DUNCAN FEDERAL #12 Oil Well Gas Well Other 2. Name of Operator JALAPENO CORPORATION 9. API Well No. 30-005-64277

3a. Address PO BOX 1608 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area ALBUQUERQUE, NM 87103 (505) 242-2050 SAN ANDRES, SOUTH 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State 2145' FNL & 694' FWL SEC. 18, T-9S, R-28E CHAVES COUNTY, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize] Deepen Production (Start/Resume) Water Shut-Off ✓ Notice of Intent Alter Casing Hydraulic Fracturing Well Integrity Reclamation Casing Repair New Construction Other Recomplete Subsequent Report Change Plans Plug and Abundon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)

it failed - Oscar Torres James January

A CASING INTEGRITY TEST HAS BEEN SCHEDULED FOR THE DUNCAN #12 WELL FOR TUESDAY, JULY 11, 2017 AT 2:00 PM.

BOB HOSKINSON WAS NOTIFIED OF THIS TEST BY PHONE AT 2:10 PM, JULY 10, 2017.

NMOCD RI 7/19/17 WIM THE CONSERVATION ARTESIA DISTRICT

Accepted for record

JUL 17 2017

ROND: NMB000378

BECEIVED

					_				•		
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Julie A. Pascal	Oil and Gas Associate										
Signature Julie a Pascal	Date		AC	ØEF	子园	okof	P	Cq	RD	/	
THE SPACE FOR FED	ERAL O	R STATE O	FIC	E US	E		_		X		
Approved by	Title			V	JUL		2017		and a	a/	Mm
Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject I which would entitle the applicant to conduct operations thereon.	nt or lease Offi	Çı:		URE C	AU OF L ARLSBA	AND M DFIELL	ANAG) OFF	EMEN ICE	T T		1
Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any false, fictitious or fraudulent statements or representations as to any matter with	any person k hin its jurisd	nowingly and viction.	iprol	y to m	ake to an	y departi	nent o	agenc	y of th	e Unite	d States

(Instructions on page 2)

JALAPENO CORPORATION

P. O. BOX 1608

ALBUQUERQUE, NM 87103

PHONE (505)242-2050, FAX (505)242-8501

FACSIMILE TRANSMITTAL SHEET							
BLM Rosv	vell	FROM: Julie A Pascal					
COMPANY:		DATI:: 7/10/17					
575-627-02	276	TOTAL NO. OF PAGES INCLUDING COVER:					
PHONE NUMBER: 575-627-0272		SENDER'S REFERENCE NUMBER:					
Duncan Fed	leral #12	YOUR R	EFERENCE NUMBER:				
URGENT	✓ FOR REVIEW	☐ PLEASE COMMENT	☐ PLEASE REPLY	□ please recycle			
NOTES/COMMENTS:							
Duncan Fede API # 30-005 Section 18, T	5-64277						

The attached Sundry Notice is to inform you of a casing integrity test for the Duncan Federal #12 well.

The test is scheduled for July 11, 2017 at 2:00 PM.

If you have any questions or need further information, you can reach Emmons Yates at the numbers listed above or by e-mail at eyates@jalapenocorp.com.

Thank you,
Julie A Pascal
Jalapeno Corporation
Oil and Gas Operations Associate